



Data Needs Analysis




Scoping Study



CR 1062, Harrison County
Bridge Replacement over
Curry Creek
Item No. 6-8710.00

Prepared by the KYTC
Division of Planning and
KYTC District 6

July 2013



I. PRELIMINARY PROJECT INFORMATION

County: Harrison Item No.: 6-8710.00
Route Number(s): CR 1062 Road Name: Robinson Union Road
Program No.: 8768701D UPN: FD04 049 1062 003-004
Federal Project No.: _____ Type of Work: Bridge Replacement
2012 Highway Plan Project Description:

Replace Robinson Union Road Bridge (12CCN) over Curry Creek at MP 3.886

Beginning MP: 3.877 Ending MP: 3.895 Project Length: 0.018

Functional Class.: ☐ Urban ☒ Rural State Class.: ☐ Primary ☐ Secondary

Local ▼

Route is on: ☐ NHS ☐ NN ☐ Ext Wt

MPO Area: Not Applicable ▼

Truck Class.: ▼

In TIP: ☐ Yes ☐ No

% Trucks: _____

ADT (current): 65 2006

Terrain: Rolling ▼

Access Control: ☒ None ☐ Permit ☐ Fully Controlled ☐ Partial Spacing: ▼

Median Type: ☒ Undivided ☐ Divided (Type): _____

Existing Bike Accommodations: Shared Lane ▼ Ped: ☐ Sidewalk

Posted Speed: ☐ 35 mph ☐ 45 mph ☐ 55 mph ☒ Other (Specify): 25 mph

KYTC Guidelines Preliminarily Based on: 30 MPH Proposed Design Speed

COMMON GEOMETRIC

Roadway Data: EXISTING PRACTICES*

No. of Lanes	<u>1 lane 2-way</u>	<u>2</u>
Lane Width	<u>12' (estimated)</u>	<u>10'</u>
Shoulder Width	<u>1' (estimated)</u>	<u>2'</u>
Max. Superelevation**	<u>N/A</u>	<u>4%</u>
Minimum Radius**	<u>N/A</u>	<u>250'</u>
Maximum Grade	<u>N/A</u>	<u>10%</u>
Minimum Sight Dist.	<u>N/A</u>	<u>200'</u>
Sidewalk Width(urban)	<u>N/A</u>	<u>N/A</u>
Clear-zone***	<u>N/A</u>	<u>7'-10'</u>

[Existing Rdwy. Plans available?](#)

☐ Yes ☒ No

Year of Plans: _____

☐ [Traffic Forecast Requested](#)

Date Requested: _____

☒ Mapping/Survey Requested

Date Requested: _____

Type: Conventional ▼

Project Notes/Design Exceptions?: Based on AASHTO Guidelines for Geometric Design of Very Low-Volume Local Roads (ADT<=400)

*Based on proposed Design Speed, **AASHTO's A Policy on Geometric Design of Highways and Streets, ***AASHTO's Roadside Design Guide

Bridge No. *: 049C00025N (Bridge #2)

Sufficiency Rating 61.1

[Existing Geotech data available?](#)

☐ Yes ☒ No

Total Length 91'

Width, curb to curb 14.6'

Detour Length(s): 11.2 miles

Span Lengths 21'

Year Built 1965

Posted Weight Limit None

Structurally Deficient? No

Functionally Obsolete? No

Existing Bridge Type Reinforced Concrete - Box Beam/Piers

*If more than two bridges are located on the project, include additions sheets.

II. PROJECT PURPOSE AND NEED

A. Legislation

This project is in the 2012-2018 Highway Plan	Funding	Phase	Year	Amount
	SPP	D	2012	\$300,000
	SPP	R	2012	\$150,000
	SPP	U	2012	\$50,000
	SPP	C	2015	\$1,000,000

B. Project Status

Work to date is limited to having a survey obtained. Design funds have been authorized.

C. System Linkage

Robinson Union Rd is a 5.327 mile local road which terminates at Poindexter Road to the south and at Robinson Road to the north. It serves farms and residences by connecting with a rural local county road network linking to the community of Cynthiana to the south and Berry to the north.

D. Modal Interrelationships

This route provides access to local residents and farms.

E. Social Demands & Economic Development

This project does not have a direct impact on future economic development.

II. PROJECT PURPOSE AND NEED (cont.)

F. Transportation Demand

CR 1062 Robinson Union Road is a one lane two-way rural local road with an ADT of 65 (2006). The road may experience more traffic during the fall because of a pumpkin patch and corn maze on the adjacent farm. The roadway serves farm and residential use. No future development is foreseen in this location.

G. Capacity


No current capacity issues. Traffic volumes are very low the majority of the year and are not expected to increase.

H. Safety

There has been one crash reported between 2007 to 2012 according to the Kentucky State Police website. This crash was on the southern approach at the abutment of the bridge. The bridge is located in an S-curve. At the southwestern curve there is a cross indicating a fatality occurred at the location, however it does not show on the State Police Report.

I. Roadway Deficiencies


The bridge crossing at Curry Creek is located between two sharp curves along CR 1062. Both the bridge and the roadway are a single lane two-way facility. The approaches on either side of the bridge are narrow and appear to be skewed. The bridge is not structurally deficient or functionally obsolete. It has a sufficiency rating of 61.1.

III. PRELIMINARY ENVIRONMENTAL OVERVIEW	
A. Air Quality Project is in: <input checked="" type="checkbox"/> Attainment area <input type="checkbox"/> Nonattainment or Maintenance Area <input type="checkbox"/> PM 2.5 County STIP Pg. #: <input type="text"/> TIP Pg. #: <input type="text"/>	
B. Archeology/Historic Resources <input checked="" type="checkbox"/> Known Archeological or Historic Resources are present Potential archeological site on hill to the east of the roadway and south of the bridge.	
C. Threatened and Endangered Species The possibility of Running Buffalo Clover, Indiana Bat habitat and mussels may be present in the area.	
D. Hazardous Materials <input type="checkbox"/> Potentially Contaminated Sites are present <input checked="" type="checkbox"/> Potential Bridge or Structure Demolition Bridge demolition required.	
E. Permitting Check all that may apply: <input type="checkbox"/> Waters of the US <input type="checkbox"/> MS4 area <input type="checkbox"/> Floodplain Impacts <input type="checkbox"/> Navigable Waters of the US Impacts Are 401/404 Permits likely to be required? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Impacts to: <input type="checkbox"/> Wetlands <input checked="" type="checkbox"/> Stream/Lake/Pond <input checked="" type="checkbox"/> ACE LON <input type="checkbox"/> ACE NW <input type="checkbox"/> ACE IP <input type="checkbox"/> DOW IWQC <input type="checkbox"/> Special Use Waters Potential impact to Curry Creek.	
F. Noise Are existing or planned noise sensitive receptors adjacent to the proposed project? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Is this considered a "Type I Project" according to the KYTC Noise Analysis and Abatement Policy? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
G. Socioeconomic Check all that may apply: <input type="checkbox"/> Low Income/Minority Populations affected <input type="checkbox"/> Relocations <input type="checkbox"/> Local Land Use Plan available No impacts to any low income or minority populations.	
H. Section 4(f) or 6(f) Resources The following are present on the project: <input type="checkbox"/> Section 4(f) Resources <input type="checkbox"/> Section 6(f) Resources No section 4(f) or 6(f) resources.	
Anticipated Environmental Document:	<div>None (Completely State funded) </div>

IV. PROJECT SCOPING, NEEDS & PURPOSE

A. Scoping & Need:

Alternate I: The bridge (049C00025N) over Curry Creek is located in a section of roadway with sharp curves and grade. Also the bridge shows impact damage to the guardrail on the bridge in multiple locations. Alternate I would reconstruct the approaches and construct a new bridge crossing to increase safety in the area. This alternate would realign the approach roads to a 30 mph design speed and relocate the bridge to the east of the current bridge.



B. Draft Project Purpose:

The purpose of the project is to increase safety on CR 1062 Robinson Union Road in the vicinity of the bridge over Curry Creek.

V. PROJECT ESTIMATE & METHODOLOGY		
Estimate Methodology:	Current Estimate	
Cost estimate is based on the cost history of similar projects of size and scope. 6-1050 bridge replacement on KY 435 in Bracken County. Total length of project was 900' with bridge size of 24'x124'. Total cost of project was \$1.4M.	<u>Phase</u>	<u>Estimate</u>
	Planning	\$0
	Design	\$150,000
	R/W	\$250,000
	Utilities	\$100,000
	Const	\$1,000,000
	Total	\$1,500,000
The new bridge would be 150'x20' located approx 100 feet to the east of the existing structure. Total length of project is about 1,100 ft. Design elements are based on Rural local road with very low volumes. Roadway will have a total width of 24' including shoulders and curves will have a design speed of 30 mph. Bridge estimate (150'x20'): \$400,000; Roadway approaches and grading (900'x24'): \$600,000		
VI. UTILITIES POTENTIALLY AFFECTED - CONTACT INFORMATION		
Company Name -	Columbia Gas	
Contact -		
Address -	2001 Mercer Rd. Lexington, KY 40511	
Phone No. -	1-800-432-9345	
Company Name -	Kentucky Utilities Co.	
Contact -		
Address -	1 Quality Street, Lexington, KY 40507	
Phone No. -	(859) 255-2100	
Company Name -	Harrison County Water Association	
Contact -		
Address -	2167 US 27, Cynthiana, KY 41031	
Phone No. -	(589) 234-4284	
Company Name -	Bell South Telephone	
Contact -		
Address -	305 Chambers Ave, Georgetown, KY 40324	
Phone No. -	(502) 863-9356	
Company Name -		
Contact -		
Address -		
Phone No. -		
Company Name -		
Contact -		
Address -		
Phone No. -		

VII. PRECONSTRUCTION STATUS REPORT

02-Apr-2013

Preconstruction Status Report

Page 200 of 207

Auth No. / Date 87687 14-Mar-2013 Project No. 06 8710.00 Parent No. 06 8710.00
County Name HARRISON
BMP / EMP 3.877 / 3.895
Route CR-1062-

Desc REPLACE UNION ROBINSON ROAD BRIDGE.(61.1)(049C00025)(12CCN)

Type Of Work BRIDGE REPLACEMENT(P) No. Lanes Length Measurement Type E

Road Eng. DEPARTMENT-D06

Bridge Eng.

Proj Mgr kytcleric.hackworth

Bridge No. C00025

Suff. Rating

Letting Status / Date *****

Final Plans

Contractor Notice

Environmental	Name	Date	Type	Sched. Comp.	Actual Comp.	Expire Date
Assigned:						
Requested:						

Concerns

EMARS PROGRAM CODE

Phase Code	D	R	U	C	
Stage	AUTHORIZED	ESTIMATED	ESTIMATED	ESTIMATED	8768701D
Fund Code	SPP	SPP	SPP	SPP	
Escalated Cost	0	150,000	50,000	1,000,000	
Fiscal Year		2012	2012	2015	
Auth Amt.	300,000				
Auth Date	14-Mar-2013				
Current Cost					
Date Of Current Cost					
Year of Proj Auth Date					
Program Code	FD04				
Remaining Balance	300,000.00				

Right Of Way Parcel Information

Utility Information

Total Parcels:	Completion Date		Completion Date
Appraisals of		Negotiated Starts of	
Relocated of		Agreement of	
Deeds Signed		Relocated of	
Suits Filed			
Right Of Entry			
Parcels Cleared			

Milestone	Remarks	Status	Date	Scheduled
PRELIMINARY LINE AND GRADE		UNKNOWN	21-May-2012	
DRAINAGE INSPECTION		UNKNOWN	21-May-2012	
JOINT INSPECTION		UNKNOWN	21-May-2012	
GEOTEC ENGINEERING - ROADWAY		UNKNOWN	21-May-2012	
GEOTEC ENGINEERING - BRIDGES		UNKNOWN	21-May-2012	
BRIDGE AND STRUCTURE PLANS TO CENTRAL OFFICE		UNKNOWN	21-May-2012	
ADVANCE SITUATION TO CENTRAL OFFICE		UNKNOWN	21-May-2012	
RIGHT OF WAY PLANS TO CENTRAL OFFICE		UNKNOWN	21-May-2012	
ROAD PLANS TO CENTRAL OFFICE		UNKNOWN	21-May-2012	
TRAFFIC PLANS - SIGNING		UNKNOWN	21-May-2012	
TRAFFIC PLANS - LIGHTING		UNKNOWN	21-May-2012	
TRAFFIC PLANS - SIGNALS		UNKNOWN	21-May-2012	
TRAFFIC PLANS - TRAFFIC CONTROL		UNKNOWN	21-May-2012	

VIII. TABLES AND EXHIBITS


Crash Information from Kentucky State Police Website

Criteria: Collision Date is between 12/31/2007 and 12/31/2012 **And** Roadway Name is Robinson Union **And** County Name is one of: HARRISON **And** Milepoint Derived is between 3 and 4



<http://crashinformationky.org/KCAP/Mapping/CollisionMap.aspx?QueryCount=1>

6/14/2013



A fatality that doesn't appear on the crash history report occurred in the sharp curve in the south approach to the bridge.

VIII. TABLES AND EXHIBITS (Continued)

North of Bridge, facing South



South of Bridge, facing North



Vertical post #3 along the left side of
the structure was found to be broken
away from the slab.

2



Sharp curve on south approach to bridge
where fatality occurred



South approach to bridge facing away from bridge



North approach to bridge facing away from bridge

NATIONAL BRIDGE INVENTORY

KENTUCKY INVENTORY AND APPRAISAL REPORT

Use of this document subject to 23 USC SEC 409

(8) STRUCTURE NUMBER: 049C00025N

*****IDENTIFICATION*****		
(1) STATENAME:	KENTUCKY	
(5) INVENTORY ROUTE (ON/UNDER):	141010620	
(2) DISTRICT AGENCY DISTRICT:	6	
(3) COUNTY CODE:	49	(4) PLACECODE: 0000
(6) FEATURES INTERSECTED:	CURRY CREEK	
(9) LOCATION:	1.6 MI S OF JCT CR 5052	
(11) MILE POINT:	3.89	
(7) FACILITY CARRIED:	ROBINSON UNION	
(12) BASE HIGHWAY NETWORK:	0 Not on the Base Network	
(13) LRS INVENTORY ROUTE & SUBROUTE		
(16) LATITUDE:	38.486350592 N DEGREES	
(17) LONGITUDE:	-84.32811517 W DEGREES	
(98) BORDER BRIDGE STATECODE	%SHARED:	Unknown
(99) BORDER BRIDGE STRUCTURE NUMBER:		

*****STRUCTURE TYPE AND MATERIAL*****		
(43) STRUCTURE TYPE MAIN:	1 Concrete / 01 Slab	
(44) STRUCTURE TYPE APPR:	Not Applicable (0)	
(45) NUMBER OF SPANS IN MAIN UNIT:	4	
(46) NUMBER OF APPROACH SPANS:	0	
(107) DECK STRUCTURE TYPE:	9 Other	
(108) WEARING SURFACE/PROTECTIVE SYSTEM		
(108A) TYPE OF WEARING SURFACE:	6 Bituminous	
(108B) TYPE OF MEMBRANE:	8 Unknown	
(108C) TYPE OF DECK PROTECTION:	8 Unknown	

*****AGE AND SERVICE*****		
(27) YEAR BUILT:	1965	
(106) YEAR RECONSTRUCTED:	0	
(42A) TYPE OF SERVICE-ON:	1 Highway	
(42B) TYPE OF SERVICE-UNDER:	5 Waterway	
(28) LANES ON STRUCTURE:	1	INDER STRUCTURE: 0
(29) AVERAGE DAILY TRAFFIC:	65	
(30) YEAR OF ADT:	2006	(109) TRUCK ADT%:
(19) BYPASS DETOUR LENGTH:	11.2 MI.	

*****GEOMETRIC DATA*****		
(48) LENGTH OF MAXIMUM SPAN:	21 ft.	
(49) STRUCTURE LENGTH:	91.2 ft.	
(50) CURB OR SIDE WALK LEFT: 0 ft.	RIGHT:	0 ft.
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	14.6 ft.	
(52) DECK WIDTH OUT TO OUT:	14.6 ft.	
(32) APPROACH ROADWAY WIDTH (W/SHOULDEI	12.1 ft.	
(33) BRIDGE MEDIAN:	0 No median	
(34) SKEW 45	(35) STRUCT FLARE:	0 No flare
(10) INVENTORY ROUTE MIN VERT CLEAR:	99.99 FT.	
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR:	10.1 ft.	
(53) MIN VERT CLEAR OVER BRIDGE RDWY:	99.99 FT.	
(54) MIN VER UNDER CLEAR REF: N	0 ft.	
(55) MIN LAT UNDER CLEAR RT REF: N	0 ft.	
(56) MIN LAT UNDER CLEAR LEFT:	0 ft.	

*****NAVIGATION DATA*****		
(38) NAVIGATION CONTROL:	Permit Not Required	
(111) PIER PROTECTION:	Not Coded	
(39) NAVIGATION VERTICAL CLEARANCE:	0 ft.	
(116) VERT-LIFT BRIDGE NAV MIN VERT CLEAREN	ft.	
(40) NAVIGATION HORIZONTAL CLEARANCE:	0 ft.	
SUFFICIENCY RATING:	61.1	
STATUS:	0 - Not Deficient	

*****CLASSIFICATION*****		
(112) NBIS BRIDGE LENGTH:	Y	
(104) HIGHWAY SYSTEM:	0 Not on NHS	
(26) FUNCTIONAL CLASS:	09 Rural Local	
(100) STRAHNET HIGHWAY:	0 Not a STRAHNET hwy	
(101) PARALLEL STRUCTURE:	No bridge exists	
(103) TEMPORARY STRUCTURE:	Not Applicable	
(102) DIRECTION OF TRAFFIC:	3 1-lane Br for 2-way	
(105) FEDERAL LANDS HIGHWAYS:	0 N/A (NBI)	
(110) DESIGNATED NATIONAL NETWORK:	0 Not part of natl netwo	
(20) TOLL:	3 On free road	
(21) MAINTAIN:	County Hwy Agency	
(22) OWNER:	County Hwy Agency	
(37) HISTORICAL SIGNIFICANCE:	5 Not eligible for NRHP	

*****CONDITION*****		
(58) DECK:	7 Good	
(59) SUPERSTRUCTURE:	7 Good	
(60) SUBSTRUCTURE:	6 Satisfactory	
(61) CHANNEL AND CHANNEL PROTECTION:	6 Bank Slumping	
(62) CULVERTS:	N N/A (NBI)	

*****LOAD RATING AND POSTING*****		
(31) DESIGN LOAD:	0 Other or Unknown	
(63) OPERATING RATING METHOD:	2 AS Allowable Stress	
(64) OPERATING RATING:	18 Tons	
(65) INVENTORY RATING METHOD:	2 AS Allowable Stress	
(66) INVENTORY RATING:	18 Tons	
(70) BRIDGE POSTING:	4 0.1-9.9%below	
(41) STRUCTURE OPEN, POSTED OR CLOSED:	A Open, no restriction	

*****APPRAISAL*****		
(67) STRUCTURAL EVALUATION:	5 Above Min Tolerable	
(68) DECK GEOMETRY:	6 Equal Min Criteria	
(69) UNDERCLEARANCE, VERT & HORIZ:	N Not applicable (NBI)	
(71) WATERWAY ADEQUACY:	7 Above Minimum	
(72) APPROACH ROADWAY ALIGNMEN	6 Equal Min Criteria	
(36) TRAFFIC SAFETY FEATURES:	0000	
(113) SCOUR CRITICAL BRIDGES:	8 Stable Above Footing	

*****PROPOSED IMPROVEMENTS*****		
(75) TYPE OF WORK:	341	
(76) LENGTH OF STRUCTURE IMPROVEMENT:	8.9 ft.	
(94) BRIDGE IMPROVEMENT COST:	116,000	
(95) ROADWAY IMPROVEMENT COST:	0	
(96) TOTAL PROJECTION COST:	115,000	
(97) YEAR OF IMPROVEMENT COST ESTIMATE:	1994	
(114) FUTURE ADT:	79	
(115) YEAR OF FUTURE ADT:	2026	

*****INSPECTIONS*****		
(90) INSPECTION DATE:	4/18/12	
(92) CRITICAL FEATURE INSPECTION:		
(92A) FRACTURE CRITICAL DETAIL:	N	
(92B) UNDERWATER INSPECTION:	N	
(92C) OTHER SPECIAL INSP:	N	
(91) FREQUENCY:	24 months	
(93) CFI DATE:		
(93A):	1/1/1901	
(93B):	5/1/2004	
(93C):	1/1/1901	

KYTC Bridge Inspection Report

Summary:

Inspection Date: 4/18/12
 Inspector: GCADY (213)
 Primary Type: Standard (24 Months)

Types of Inspections Performed:

National Bridge Inventory: Y
 Element: Y
 Fracture Critical: N
 Underwater: N
 Other Special: N

Inspector Signature: _____

District Review Date: 7/2/12

District Reviewer: BSEITER (55)

IDENTIFICATION

Bridge ID (8):	049C00025N	District Number:	6
Route Carried (7):	ROBINSON UNION	County (3):	49 Harrison
Mile Point:	3.886	Feature Intersected (6):	CURRY CREEK
Location (9):	1.6 MI S OF JCT CR 5052	Road Name:	ROBINSON UNION RD
Structure Description:	91.2 Foot - 4 Span Concrete Slab		

NBI CONDITION

SCHEDULE TAB

Deck (58):	7	Schedule:	Required (Y/N)	Last Date	Frequency	Next Date
Superstructure (59):	7	NBI (90):		4/18/12	(91): 24 mos	4/18/14
Substructure (60):	6	Fracture Critical (92A):	N	(93A): 1/1/01	(92A): mos	1/1/01
Culverts (62):	N	Underwater (92B):	N	(93B): 5/1/04	(92B): mos	1/1/01
Channel/Protection (61):	6	Other Special (92C):	N	(93C): 1/1/01	(92C): mos	1/1/01
		Elemental:	NA		24 mos	4/18/14

Load Rating and Posting

WATERWAY

Truck Type	Typ I	Typ II	Typ III	Typ IV	Gross	Scour Critical (113):	8
Recomm. Posting:	18	18	18	18	18	Observed 113 Rating:	5
Field Posting:	-1	-1	-1	-1	0	Waterway Adeq. (71):	7
Posting Status (41):	A Open, no restriction						
Signs Posted:	Cardinal:	N	Non-Cardinal:	N			

DECK/WEARING SURFACE

Deck Type (107):	9 Other						
Wearing Surface/Protective System (108):	Type:	6	Membrane:	8	Protection:	8	
Traffic Safety Features (36):	Bridge Rail:	0	Transition:	0	Appr. Rail:	0	Rail Ends: 0
Overlay:	Y						
Overlay Type:	Asphalt	(34) Skew:	45				
Overlay Thickness:	2.99	(51) Curb-to-Curb Width:	14.6				

Vertical Clearances

Minimum Vertical Overclearance (53):	99.99
Minimum Vertical Underclearance (54):	0.00
Maximum Vertical Clearance (10):	99.99
Minimum Vertical Clearance:	99.99

Sufficiency Ratings

SR:	61.1	SD/FO:	0 Not Deficient
-----	------	--------	-----------------

Element Condition State Data

Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5
104/3	P/S Conc Box Girder	LF	91.19	91.19	0.00	0.00	0.00	0.00
13/3	Unp Conc Deck/AC Ovl	SF	364.80	364.80	0.00	0.00	0.00	0.00

KYTC Bridge Inspection Report

Summary:

Inspection Date: 4/18/12
 Inspector: GCADY (213)
 Primary Type: Standard (24 Months)

Types of Inspections Performed:

National Bridge Inventory: Y
 Element: Y
 Fracture Critical: N
 Underwater: N
 Other Special: N

Element Condition State Data

Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5
210/3	R/Conc Pier Wall	LF	72.75	47.75	25.00	0.00	0.00	0.00
215/3	R/Conc Abutment	LF	72.85	47.85	25.00	0.00	0.00	0.00
301/3	Pourable Joint Seal	LF	8.49	8.49	0.00	0.00	0.00	0.00
334/3	Metal Rail Coated	LF	182.40	152.40	20.00	0.00	0.00	10.00
359/3	Soffit Smart Flag	EA	1.00	0.00	1.00	0.00	0.00	0.00
361/3	Scour Smart Flag	EA	1.00	1.00	0.00	0.00	0.00	0.00
39/3	Unp Conc Slab/AC Ovl	SF	962.20	962.20	0.00	0.00	0.00	0.00
504/3	Wearing Surface	SQ FT	1327.00	1327.00	0.00	0.00	0.00	0.00
608/3	Long. Shear Keys	EA	1.00	1.00	0.00	0.00	0.00	0.00
610/1	Chan Drift	EA	1.00	1.00	0.00	0.00	0.00	0.00
611/1	Embankment Erosion	EA	1.00	1.00	0.00	0.00	0.00	0.00
612/1	Chan Algn	EA	1.00	1.00	0.00	0.00	0.00	0.00

Element Condition State Data

Str	Uni	Elm/Env	Description	Description
1	104/3	P/S Conc Box Girder	Box Beam*	There is one precast prestressed box beam that has been added next to left side of slab in order of widen the structure. Along the bottom interior portion of this beam is a longitudinal joint that is allowing some staining and efflorescence along the bottom of the beam and slab elements. The tie rod ends along the left exterior portion of the beam is in place. See Photos
1	13/3	Unp Conc Deck/AC Ovl	Deck*	The top side of the deck could not be viewed for inspection due to asphalt overlay. See Photos
1	210/3	R/Conc Pier Wall	Pier Walls*	Efflorescence and staining was found throughout all pier wall elements. Areas of horizontal cracking with efflorescence were found along the top portions of the # 3 pier wall. The right side of the piers have been extended rightward to support the additional width of one box beam element added during a widening project. During the widening project the a concrete slurry was poured out along the right forward side of the pier # 2 extension that is now undermined up to 18" See Photos
1	215/3	R/Conc Abutment	Abutments*	A minor amount of staining and efflorescence was noted on the abutment breast walls due to seepage from above. The abutment breast walls were also found to have random areas of vertical hairline cracking. The right side of the abutments have been extended leftward to support the additional width of one box beam element added during a widening project. See Photos
1	301/3	Pourable Joint Seal	Pourable Joint*	The pourable joints are located only between the box elements over the pier locations. Joints could not be viewed from top side due to asphalt overlay.

Summary:

Inspection Date: 4/18/12
 Inspector: GCADY (213)
 Primary Type: Standard (24 Months)

Types of Inspections Performed:

National Bridge Inventory: Y
 Element: Y
 Fracture Critical: N
 Underwater: N
 Other Special: N

Element Condition State Data

Str	Uni	Elm/Env	Description	Description
1	334/3	Metal Rail Coated	Bridge Railing*	Both of the rear and forward bridge railing end treatments were found to have been damaged by roadway traffic impact. The bridge railing was noted to have multiple scrapes and scratches from traffic impact as well. The bridge railing post located in the third position from the rear end along the left side of the structure was found to have the concrete around the anchor bolts broken completely away, giving the post no support. Two bolts were found to be missing from the top portion of the right side bridge railing system at approximately mid span. See Photos
1	359/3	Soffit Smart Flag	Soffit*	Longitudinal cracking with efflorescence was noted randomly throughout the deck soffit. See Photos
1	361/3	Scour Smart Flag	Scour*	Underpinning along the forward portion of the # 2 pier wall was found to be undermined up to 18".
1	39/3	Unp Conc Slab/AC Ovl	Deck*	The top side of the deck could not be viewed for inspection due to asphalt overlay. See Photos
1	504/3	Wearing Surface	Wearing Surface*	The top side of the deck could not be viewed for inspection due to asphalt overlay. The asphalt wearing surface was found to have a minor amount of vegetation growth along with roadway dirt and debris along the exterior edges. See Photos
1	608/3	Long. Shear Keys	Longitudinal Joint*	Along the bottom interior portion of the beam is a longitudinal joint that is allowing some staining and efflorescence along the bottom of the beam and slab elements. See Photos
1	610/1	Chan Drift	Channel Drift*	A minor amount of channel drift and debris was found to be lodged along the left most portions of piers # 2, 3 and 4. See Photos
1	611/1	Embankment Erosion	Erosion*	A minor amount of soil erosion was found behind all four wingwall elements. See Photos
1	612/1	Chan Algn	Channel Alignment*	Minor aggregation and vegetation build-up noted to be causing the stream to migrating toward the rear of the structure, and the majority of the streams energy is going through only the second span. See Photos

Structure Notes

Linear feet of pourable joint material should be measured during next inspection.

Inspection Notes

May want to consider replacing scour protection system along the forward portion of the # 2 pier.

Work Candidates

Inspector Candidates:

Candidate ID:	Status	Priority	Assigned	Action	Elem	Date Recommended
049-C00025N-1	Approved	Medium	Unassigned	40	610	4/18/12
049-C00025N-2	Approved	Medium	Unassigned	24	361	4/18/12
049-C00025N-3	Approved	High	Unassigned	31	334	4/18/12

Summary:
Inspection Date: 4/18/12
Inspector: GCADY (213)
Primary Type: Standard (24 Months)

Types of Inspections Performed:
National Bridge Inventory: Y
Element: Y
Fracture Critical: N
Underwater: N
Other Special: N

Work Candidates						
Inspector Candidates:						
Candidate ID:	Status	Priority	Assigned	Action	Elem	Date Recommended
049-C00025N-4	Approved	High	Unassigned	33	504	4/18/12
049-C00025N-5	Approved	Medium	Unassigned	40	612	4/18/12