

# US68 Lawrence Creek Bridge



## Embankment Settlement & Proposed Solutions

ACEC-KY/FHWA/KYTC Partnering Conference

Louisville, Kentucky

September 4, 2019

# Project Team



**KENTUCKY  
TRANSPORTATION  
CABINET**

**AECOM**



**GEOTECHNOLOGY** INC.  
FROM THE GROUND UP

# Outline

- Project Background
- Geotechnical Investigation
- Bridge Evaluation
- Proposed Solutions



# Project Background



## Project Background

# John P. Loyd Memorial Bridge


### Project Data

- 766-ft Length
- ADT is 4,800
- Urban Principal Arterial
- Design 1994
- Constructed 1996-1997




## Project Background

## Site Location



## Project Background

## Site Location



US 68 Lawrence Creek Bridge

## Project Background

# Ohio River Crossings in Maysville



US 68 Lawrence Creek Bridge



## Project Background

## Site Location



## Project Background


# Adjacent Crossings



US 68 Lawrence Creek Bridge

# Project Background

# Bridge Elevation



**Abutment 1**

**Pier 2**

**Pier 3**


**Pier 4**

**Pier 5**

**Abutment 6**

# Project Background

## Bridge Plan



## Project Background

### Bridge Problems – Issues from Day 1



## Project Background

### Bridge Problems – July 2014



US 68 Lawrence Creek Bridge

## Project Background

# Bridge Problems – July 2014



## Project Background

### Bridge Problems – July 2014



## Project Background

# Bridge Problems – 2016



US 68 Lawrence Creek Bridge

## Project Background

# Bridge Problems – 2016



US 68 Lawrence Creek Bridge

## Project Background

# Bridge Problems – 2016



## Project Background

# Bridge Problems – 2016



US 68 Lawrence Creek Bridge

## Project Background

# Bridge Problems – 2016



## Project Background

# Bridge Problems – 2016



## Project Background

### Bridge Problems – 2016



**Photo 58.7-3: West railing at Abutment 6 misaligned transversely 1 inch to the west**



**Photo 58.7-4: East railing at Abutment 6 misaligned transversely 1½ inch to the west**

## Project Background

### Bridge Problems – July 2016



## Project Background

# Bridge Problems – Facts & Rumors

- **Value Engineering**
  - Apparent Minimum Design Tolerances
- **Construction Issues**
- **No As-Built Plans**
  - Including Pile Driving Records



## Project Background

# Proceed to Find a Solution

### RFP for Design Services

- RFP -> October 2016
- NTP -> March 2017
- AECOM / Geotechnology

### Scope of Work

- Review of Project Documents
- Surveying / Monitoring
- Bridge Inspection
- Geotechnical Investigation
- Structural Analysis
- Evaluation of Rehabilitation Alternatives
- Report Preparation
- Final Design



# Geotechnical Investigation



## Geotechnical Investigation

### Project Scope

#### 2017 Fieldwork


- 14 geotechnical borings
  - 3 offset holes at Hole 1003, 1010, and 1011
- 4 slope inclinometers installed at Holes 1004, 1006, 1009, and 1011A
- Modified Sondex installations in Holes 1004 and 1011A for settlement monitoring

#### Analysis

- Embankment Analysis
- Slope Stability Analysis
- Settlement Analysis
- Batter Pile Analysis
- Pile Downdrag Analysis

# Geotechnical Investigation

## Instrumentation



US 68 Lawrence Creek Bridge

## Geotechnical Investigation

# Subsurface Conditions

### Bedrock Formations

- Kope Formation: 80% Shale & 20% Limestone
- Fairview Formation: 60% Limestone & 40% Shale
- Grant Lake Limestone: 65-85% Limestone & 15-35% Shale

### Shot-rock Fill

- Comprised of Grant Lake Limestone & Fairview Formation

### Pile Core Material


- No. 57 stone

### Driven Piles

- Bear in Kope Formation

# Geotechnical Investigation

## Abutment 1 – South Embankment




# Geotechnical Investigation

## Abutment 6 – North Embankment

COUNTY OF	ITEM NO.	SHEET NO.
MASON	9-1095	-----

ASSUMED SOIL STRENGTH PARAMETERS				
MATERIAL ID	MATERIAL DESCRIPTION	1993 PARAMETERS	2017 LINEAR PARAMETERS	2017 NONLINEAR PARAMETERS
1	GRANT LAKE LIMESTONE FORMATION FILL	$\gamma = 125$ pcf $c' = 0$ psf $\phi' = 40^\circ$	$\gamma = 125$ pcf $c' = 0$ psf $\phi' = 30^\circ$	$\gamma = 125$ pcf $t' = 0.820 (c')^{0.504}$
2	PILE CORE	$\gamma = 125$ pcf $c' = 0$ psf $\phi' = 38^\circ$	$\gamma = 100$ pcf $c' = 0$ psf $\phi' = 32^\circ$	$\gamma = 100$ pcf $c' = 0$ psf $\phi' = 32^\circ$

FACTORS OF SAFETY		
1993 PARAMETERS	A	1.65
2017 LINEAR PARAMETERS - OUTSIDE OF PILE CORE LIMITS	B	1.26
2017 NONLINEAR PARAMETERS - OUTSIDE OF PILE CORE LIMITS	C	1.28
2017 LINEAR PARAMETERS - 20' DEEP FAILURE AT PIER 5	D	1.22
2017 NONLINEAR PARAMETERS - 20' DEEP FAILURE AT PIER 5	E	1.25



USER: \_\_\_\_\_ DATE PLOTTED: October 10, 2017  
 PROJECT: US 68 LAWRENCE CREEK BRIDGE CROSS SECTIONS  
 SHEET NAME: E-SHEET NAME: \_\_\_\_\_  
 PROJECT NO: 117-443

## Geotechnical Investigation

### Slope Stability

Scenario	Factor of Safety
<b>South Embankment (Abutment 1)</b>	
2017 linear parameters – outside of pile core limits	1.21
2017 nonlinear parameters – outside of pile core limits	1.20
2017 linear parameters – 20-foot-deep failure at Pier 2	1.18
2017 nonlinear parameters – 20-foot-deep failure at Pier 2	1.18
<b>North Embankment (Abutment 6)</b>	
2017 linear parameters – outside of pile core limits, 20-foot-deep failure	1.26
2017 nonlinear parameters – outside of pile core limits, 20-foot-deep failure	1.28
2017 linear parameters – 20-foot-deep failure at Pier 5	1.22
2017 nonlinear parameters – 20-foot-deep failure at Pier 5	1.25

## Geotechnical Investigation

### Settlement

Location	Embankment Height, H (ft.)	Observed Settlement (in.)		Shale Settlement from Hopkins and Beckham, $H_{SS}$ (in.)	
		Ground Surface <sup>a</sup>	Beneath Pile Cap <sup>b</sup>	At Ground Surface	At Top of Pile
South Approach	115	30 <sup>c</sup>	N/A	32.1	N/A
Abutment 1	103	20-25	<b>16-28</b>	24.4	<b>24.4</b>
Pier 2	56	N/A	<b>2-4<sup>d</sup></b>	5.3	<b>4.6</b>
Pier 5	70	N/A	<b>2-8<sup>d</sup></b>	9.3	<b>8.8</b>
Abutment 6	104	26-29	<b>13-30</b>	24.9	<b>24.9</b>
North Approach	115	27 <sup>c</sup>	N/A	32.1	N/A

<sup>a</sup> Ground surface settlements were interpreted from the concrete paint coatings on the abutments and the pavement cores in the approach slabs.



<sup>b</sup> Measured from the test pits.

<sup>c</sup> Settlement at the approach slabs assumes the original approach slab thickness was 12 inches.

<sup>d</sup> Beneath the pile caps at Piers 2 and 5, the settlements were greater around the perimeter in the area of the batter piles and lesser in the interior areas between piles.

## Geotechnical Investigation


### Settlement Profile – Abutment 6 (Hopkins & Beckham 1998)



# Geotechnical Investigation

## Boring 1011A Sondex Instrumentation at Abutment 6

### Settlement Profile at Boring 1011A






# Geotechnical Investigation

## Battered Pile Analyses– (Shibata et al 1992)

### Battered piles analyses for evaluating bending moment:

- Empirical method by Shibata et al (1992)
- LPILE method (USACE 2012)
- FEM using SIGMA/W



## Geotechnical Investigation

### Summary of Findings

Deformation of shot-rock fill resulted from:

- Softening of shale
- Rearrangement of particles from groundwater infiltration
- Collapsing of nested limestone or shale that bridged voids

Lateral movements and structural distress of bridge abutments resulted from:

- Bending of batter piles, which “pulled” creek side of pile caps down and towards the creek
- Time-dependent horizontal deformations within the fill, related to primary compression of the shot-rock fill, which “pushed” the piles towards the creek

Slope Stability:

- Signs of global stability were not visible
- Factor of safety for long-term conditions = 1.2 for north and south embankments
- Typical target values for the factor of safety are between 1.6 and 1.8

## Geotechnical Investigation

### Summary of Findings

#### Settlements

- Observed settlements are in reasonable agreement with settlements computed by Hopkins and Beckham equation
- Effects of embankment deformation on existing pile foundations per empirical and finite element (FE) analysis methods:
  - Abutments 1 & 6 and Piers 2 & 5:
  - Additional deep foundations should be provided to improve the factor of safety and provide additional resistance for potential continued settlement of the fill embankment



# Bridge Evaluation



## Bridge Evaluation

### Scope of Work

- Review of Project Documents
- Surveying / Monitoring
- Bridge Inspection
- Geotechnical Investigation
- Structural Analysis
- Evaluation of Rehabilitation Alternatives
- Report Preparation
- Final Design



## Bridge Evaluation

# Survey & Monitoring

## BTM Engineering

### Baseline

- Ground Topography
- Embankment Monitoring Locations
- Structure Monitoring Locations
- Roadway Elevations
- LiDAR Scan

### Quarterly Comparisons



## Bridge Evaluation

# Embankment monitoring




# Bridge Evaluation

## Embankment monitoring



### $\Delta$ Elevation - South Embankment (ft)



## Bridge Evaluation

### LiDAR scan



US 68 Lawrence Creek Bridge

## Bridge Evaluation

# Conclusions and Recommendations

### Summary

- Slope Stability
- Structural Observations
- Embankment Settlement
- Pile Distress

### Recommendations

- Reconstruct Abutments 1 & 6
- Strengthen Piers 2 & 5
- Increased Inspection & Monitoring Cycle



# Proposed Solutions



## Proposed Solutions

### Project Team Goals

- Address evaluation recommendations
- Correct deterioration in abutment caps, end diaphragms, and piles
- Account for future settlement in deep foundation design
- Provide ongoing traffic service during construction



## Proposed Solutions

### Remediation Alternatives

- **No Build**
  - Inexpensive
  - Does not address problem
- **Long Term Monitoring**
  - Inexpensive
  - Can alert KYTC of problems
  - Does not address damaged structural concerns.
- **Complete Reconstruction**
  - Expensive
  - No benefit in addressing geotechnical challenges
- **Rehabilitation & Strengthening**
  - Bridge can maintain in-service
  - Constructability challenges



## Proposed Solutions

# Abutment Rehabilitation & Strengthening Alternatives



- **Abutment Strengthening**
  - Center of Cap
  - Widening the Cap
- **Abutment Reconstruction**
  - In-situ
  - Behind Existing Abutment
  - In-front Existing Abutment
- **Deep Foundation Support**
  - Battered H-piles
  - H-piles
  - Drilled Shafts
  - Micropiles







## Proposed Solutions

# Abutment Strengthening



## Proposed Solutions


# Abutment Reconstruction



## Proposed Solutions

# Abutment Deep Foundation Alternatives


- **Battered H-piles**
  - Continued downdrag problems
- **Vertical H-piles**
  - Requires downdrag isolation casings
  - Large diameter similar to shaft option
- **Drilled Shafts**
  - Large diameter attracts significant downdrag loads
  - Requires deep rock socket
- **Micropiles**
  - Small diameter can be installed in between existing piles and girders



## Proposed Solutions


### Pier Strengthening

- **Piers 2 & 5**
  - Downdrag
- **Raft Footings**
  - 10 battered piles
  - 6 vertical piles
- **Strengthening**
  - Design to support 100% load




# Proposed Solutions

## Pier Strengthening



## Proposed Solutions

# Pier Strengthening



## Proposed Solution

# Construction

- **Schedule**
  - October 25, 2019 Letting
  - Completion in 2021



Questions?

