



# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter


Entered by: DCOULTER

12/03/2024

Standard (24 months)

<u>IDENTIFICATION</u>			
Structure Num (8):	056B00211N		
NBI Number	056B00211N		
Structure Name:			
Location (9):	0.6 MI N OF I-264		
Carries (7):	I-65		
Type of Service (42A):	1 Highway		
Feature Crossed (6):	KFEC GATE 6 DR		
Type of Service (42B):	1 Highway		
Placecode (4):	Not Applicable		
County (3):	Jefferson (056)		
State (1):	21 Kentucky		
Admin Area:	Inventory		
District:	District 5		
Latitude (16):	38° 11' 56"		
Longitude (17):	85° 44' 3"		
Owner (22):	State Highway Agency		
Maint. Resp. (21):	State Highway Agency		
Year Built (27):	1957	Border State (98A):	Not Applicable (P)
Year Recon (106):	1985	Border Number (99):	
		% Responsibility (98B):	

<b>Fair</b>		Heath Index:	69.15
SubStd: No		SubStd Reason:	Not Sub-Standa
Inspection Type	Freq (92)	Last Insp (93)	Next Insp
Routine	24	12/3/2024	12/3/2026
Element	24	12/3/2024	12/3/2026
Fracture Critical (A)		1/1/1901	1/1/1901
Underwater (B)		1/1/1901	1/1/1901
Special Insp (C)		1/1/1901	1/1/1901
<u>LOAD RATING AND POSTING</u>			
Posting Status(41):		A Open, no restriction	
Posting (70):		5 At/Above Legal Loads	
Signs Posted Cardinal:		No	
Signs Posted Non-Cardinal:		No	
Recmd Date:		Posted Date:	
<u>Required Postings (Tons.)</u>		<u>Field Postings (Tons.)</u>	
Gross:		Gross:	
Truck Type 1:		Truck Type 1:	
Truck Type 2:		Truck Type 2:	
Truck Type 3:		Truck Type 3:	
Truck Type 4:		Truck Type 4:	
SUV 5:		SUV 5:	
SUV 6:		SUV 6:	
SUV 7:		SUV 7:	
EV Single Axle:		EV Single Axle:	
EV Tadem Axle:		EV Tadem Axle:	
EV Gross:		EV Gross:	

<u>DECK GEOMETRY</u>	
Deck Geometry (68):	7 Above Min Criteria
Deck Area:	18,863.00 ft²
Deck Type (107):	1 Concrete-Cast-in-Place
Wearing Surface (108A):	6 Bituminous
Membrane (108B):	0 None
Deck Protection (108C):	1 Epoxy Coated Reinforci
Approach Roadway width (32):	120.00 ft.
Width Curb to Curb (51):	119.30 ft.
O. to O. Width (52):	125.00 ft.
Curb / Sidewalk Width L (50A):	0.00 ft.
Curb / Sidewalk Width R (50B):	0.00 ft.
Median (33):	3 Closed Med w/Barriers
	
<u>DECK CONDITION</u>	
Deck Rating (58):	5 Fair
Bridge Rail (36A):	0 Substandard
Transition (36B):	0 Substandard
Approach Rail (36C):	0 Substandard
Approach Rail Ends (36D):	0 Substandard



# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter


Entered by: DCOULTER

12/03/2024

Standard (24 months)

## SUPERSTRUCTURE GEOMETRY

# of Main Spans (45): 3  
# of Approach Spans (46): 0  
Main Material (43 A): 4 Steel Continuous  
Main Design (43 B): 02 Stringer/Girder  
Max Span Length (48): 65.50 ft.  
Structure Length (49): 150.90 ft.  
NBIS Length (37): Long Enough  
Temp Structure (103): Not Applicable (P)  
Skew (34): 2°  
Structure Flared (35): 0 No flare  
Parallel Structure (101): No || bridge exists  
Approach Alignment (72): 8 Equal Desirable Crit




## SUPERSTRUCTURE CONDITION

Superstructure Rating (59): 5 Fair  
Structure Evaluation (67): 5 Above Min Tolerable

## SUBSTRUCTURE GEOMETRY

Navigation Control (38): NA-no waterway  
Nav Vert Clearance (39): 0.00 ft.  
Nav Horiz Clearance (40): 0.00 ft.  
Pier Protection (111): Not Applicable (P)  
Lift Bridge Vertical Clearance (116):  
Scour Rating (113): N Not Over Waterway  
Waterway Adequacy (71): N Not applicable



## SUBSTRUCTURE CONDITION

Substructure Rating (60): 5 Fair  
Channel Rating (61): N N/A (NBI)

## KYTC FIELDS

Overlay:	Yes	Scour Observed:	N/A
Overlay Type:	L T Polymer Asph	Scour Risk :	N/A
Overlay Thickness:	2.25 in.	Scour Analysis/Assessment :	Not Required
Overlay Year:	2012	Scour POA :	Not Required
Cross Section:	Not Required	Scour POA Date :	
Cross Section Date:		Next Cross Section Due Date :	

## 1ST NON-CARD ROUTE ON: I-65 NC

ROADWAY LOCATION		ROADWAY CLASSIFICATION		CLEARANCES	
Pos Prefix (5A):	1st Non-Card Route	Funct Class (26):	11 Urban Interstate	Vertical (10):	99.99 ft.
Kind of Hwy (5B):	1 Interstate Hwy	Level Service (5C):	1 Mainline	Min Vert Over (53):	99.99 ft.
Route Num (5D):	00065	NHS (104):	1 On the NHS	Vert Ref (54A):	H Hwy beneath struct
LRS Route (13A/B):	IO0065_000/00	Defense Hwy (100):	1 On Interstate STRAHNET	Undrclearance (54B):	14.75 ft.
Milepost (11):	131.40 mi	Toll Facility (20):	3 On free road	Horizontal (47):	59.67 ft.
Suffix (5E):	0 N/A (NBI)	ADT (29):	129,829 Cars/Day	Min Lat Left (56):	0.00 ft.
Lanes Under (28B):	8	Pct Trucks (109):	12.00%	Min Lat Right (55B):	5.30 ft.
Detour Length (19):		ADT Year (30):	2022	Horiz Ref (55A):	H Hwy beneath struct
				Underclearance (69):	3 Intolerable - Correct



# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter

Entered by: DCOULTER

12/03/2024

Standard (24 months)

## ROUTE UNDER STRUCTURE: KFEC GATE6 DR

ROADWAY LOCATION		ROADWAY CLASSIFICATION		CLEARANCES	
Pos Prefix (5A):	One Route Under	Funct Class (26):	19 Urban Local	Vertical (10):	14.83 ft.
Kind of Hwy (5B):	7 State Lands Road	Level Service (5C):	0 None of the below	Min Vert Over (53):	99.99 ft.
Route Num (5D):	08402	NHS (104):	0 Not on NHS	Vert Ref (54A):	H Hwy beneath struct
LRS Route (13A/B):		Defense Hwy (100):	0 Not a STRAHNET hwy	Undrclearnce (54B):	14.75 ft.
Milepost (11):	0.08 mi	Toll Facility (20):	3 On free road	Horizontal (47):	48.00 ft.
Suffix (5E):	0 N/A (NBI)	ADT (29):	1,558 Cars/Day	Min Lat Left (56):	0.00 ft.
Lanes Under (28B):	4	Pct Trucks (109):	-1.00%	Min Lat Right (55B):	5.30 ft.
Detour Length (19):		ADT Year (30):	2006	Horiz Ref (55A):	H Hwy beneath struct
				Underclearance (69):	3 Intolerable - Correct

## ROUTE ON STRUCTURE: I-65

ROADWAY LOCATION		ROADWAY CLASSIFICATION		CLEARANCES	
Pos Prefix (5A):	Route On Structure	Funct Class (26):	11 Urban Interstate	Vertical (10):	99.99 ft.
Kind of Hwy (5B):	1 Interstate Hwy	Level Service (5C):	1 Mainline	Min Vert Over (53):	99.99 ft.
Route Num (5D):	00065	NHS (104):	1 On the NHS	Vert Ref (54A):	H Hwy beneath struct
LRS Route (13A/B):	IO0065_000/00	Defense Hwy (100):	1 On Interstate STRAHNET	Undrclearnce (54B):	14.75 ft.
Milepost (11):	131.40 mi	Toll Facility (20):	3 On free road	Horizontal (47):	59.70 ft.
Suffix (5E):	0 N/A (NBI)	ADT (29):	129,829 Cars/Day	Min Lat Left (56):	0.00 ft.
Lanes On (28A):	8	Pct Trucks (109):	12.00%	Min Lat Right (55B):	5.30 ft.
Detour Length (19):	0.00 mi	ADT Year (30):	2022	Horiz Ref (55A):	H Hwy beneath struct
				Underclearance (69):	3 Intolerable - Correct



## Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter

Entered by: DCOULTER

12/03/2024

Standard (24 months)

### STRUCTURE NOTES

- In 2023, AECOM used infrared thermography to identify and locate areas of concrete delamination and overlay debonding in the deck, plus they obtained core samples for testing to determine chloride ion levels in the concrete. See Media tab for results.
- 2017 project (CID 174301) included asphalt plug joints.
- 2012 project (CID 121305) included the following: 1. 2.25" asphalt waterproofing mix overlay (low temp. product by "Road Science" - not Rosphalt), 2. median barriers were replaced with single taller barrier, 3. asphalt plug joints were installed over the existing joints, and 4. repair of "distressed" areas.
- In 2001, a detailed visual inspection was performed on this structure.
- Structure was widened in 1987 (Drawing No. 18877). Field measurements do not match plan dimensions.
- The deck was overlaid in 1981.

### INSPECTION NOTES

- Routine inspection performed by Daniel Coulter and Stephanie Stoops.
- DBE was notified on 12/03/24 about the erosion hole along the roadway at the NW corner.

### SCOUR NOTES

### LOAD RATING NOTES

8/31/2015 Controlling member is original beams 3-6 in SB or NB or beam 3 SB/ beam 7 NB with 2.25" asphalt, 1.5" latex overlay, modified barriers, and no provision for FWS. Critical point is 2.5 (midspan of span 2) for all trucks. Rating SU4: 47.2 tons (RF 1.75) SU5: 49.8 tons (RF 1.61) SU6: 50.3 tons (RF 1.45) SU7: 52.0 tons (RF 1.34). DGA

### COMPLIANCE NOTES





# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter

Entered by: DCOULTER

12/03/2024

Standard (24 months)

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
12	Re Concrete Deck	3	12/03/2024	18,877.00	sq.ft	14,277.00	4,000.00	600.00	0.00

The top of the deck cannot be inspected due to asphalt overlay. The underside has transverse cracks with efflorescence and moderate width cracks at the bridge ends. The underside of the deck adjacent to the Abutment 1 joint is in poor condition, especially from Bays 15 through 17, and has spalling with exposed rebar with portions of spalls resting on top of the diaphragms. There are a few other spalls with exposed rebar, mostly below the longitudinal joint, and haunch spalls along the beam top flanges. Separation of deck and top flange was observed at several beam ends at Abutment 1 (deck deflected under live load while beams remained stationary).

813 AC Wearing Surf w/ 3 12/03/2024 18,002.00 sq.ft 18,000.00 0.00 2.00 0.00  
Membrane

Asphalt overlay has cracking in the SB right lane at the north bridge end. There is minor debris in the shoulders.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
107	Steel Opn Girder/Beam	3	12/03/2024	3,319.00	ft	1,541.00	1,503.00	275.00	0.00

The beams have painted over pitting, with some areas of minor section loss, in the bottom flange scattered throughout. The beam ends have laminating corrosion at the abutments and at haunch spalls. The beams have scattered surface corrosion throughout, mostly along the top and bottom flanges. Beam 17 has a 3/8" T x 1'-3" L distortion in the bottom flange near Abutment 1. The welded bottom cover plates contain a fatigue sensitive detail, Category E, and Beam 5 in Span 1 near Pier 2 has some surface corrosion at the end weld. Previous in-depth inspections noted cracks in the stiffener to top flange tack welds (some are visible from the abutments) (concurrent CS2).

515 Steel Protective Coating 3 12/03/2024 26,552.00 sq.ft 16,852.00 8,000.00 200.00 1,500.00

The steel protective coating has areas of dulling (8000 sq.ft CS2) and has no effectiveness where corrosion is present (1500 sq.ft CS4). The paint is flaking and peeling in a few areas, mostly on the top of the bottom flanges near the abutments (200 sq.ft CS3).

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
205	Re Conc Column	3	12/03/2024	20.00	each	0.00	17.00	3.00	0.00

The columns have moderate width vertical and horizontal cracks, abrasion with exposed coarse aggregate, scrapes, and small spalls with occasional exposed tie wire. Pier 2 Column 3 has scaling with missing coarse aggregate at the bottom. Pier 2 Column 10 has a shallow spall in the east face. Pier 3 Column 9 has a shallow spall.



# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter

Entered by: DCOULTER

12/03/2024

Standard (24 months)

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
215	Re Conc Abutment	3	12/03/2024	252.00	ft	89.00	60.00	103.00	0.00

Abutment 1 backwall has wide diagonal cracks at the ends and a spall with exposed rebar adjacent to Beam 11. Abutment 1 has heavy debris on top of the cap, especially near the east end. The Abutment 4 backwall has widespread patching with some large unsound areas, spalling with exposed rebar, and moderate width cracks. The Abutment 4 cap has wide horizontal cracks in the front face below Beams 15, 17 and 20.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
234	Re Conc Pier Cap	3	12/03/2024	238.00	ft	216.00	21.00	1.00	0.00

Pier caps have moderate width vertical cracks, delaminations, and shallow spalls. The Pier 3 cap has a wide crack in the bottom face between Columns 1 and 2 adjacent to the construction joint.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
306	Other Joint	3	12/03/2024	240.00	ft	0.00	26.00	40.00	174.00

The asphalt plug joints are located at Abutments 1 & 4, installed over the existing joints in 2012, and redone in 2017. The plug joints have failed in several areas of the traffic lanes, exposing portions of the original joints and allowing free flow of water through the joints. The Abutment 4 joint on the NB side has some areas where the joint is starting to break up. The joints are partially filled with debris and have some minor cracking.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
311	Moveable Bearing	3	12/03/2024	66.00	each	0.00	7.00	58.00	1.00

Abutment 1 bearings are over-expanded and all bearings have corrosion, many with section loss. At Abutment 1, several girder sole plates are not fully bearing on the rocker bearings and bang under live load (most notably at Girders 15, 17, and 18). Many bearings at Abutment 1 are slightly misaligned, and some of the masonry plates no longer sit flush on the abutment seat due to extensive pack rust. Rocker bearings are over-expanded at Pier 2 and some bearings have freckling rust. Abutment 4 bearings have corrosion, some with section loss. Abutment 4 bearings have inconsistent rotations throughout.

515	Steel Protective Coating	3	12/03/2024	330.00	sq.ft	0.00	0.00	110.00	220.00
-----	--------------------------	---	------------	--------	-------	------	------	--------	--------

The protective coating has no effectiveness at the abutments (220 sq.ft CS4) and limited effectiveness at Pier 2 (110 sq.ft CS3).



# Bridge Inspection Report

056B00211N

Inspector: Daniel Coulter

Entered by: DCOULTER

12/03/2024

Standard (24 months)

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
313	Fixed Bearing	3	12/03/2024	22.00	each	20.00	2.00	0.00	0.00

The exterior fixed bearings at Pier 3 have surface corrosion.

515	Steel Protective Coating	3	12/03/2024	44.00	sq.ft	40.00	0.00	0.00	4.00
-----	--------------------------	---	------------	-------	-------	-------	------	------	------

Steel protective coating has no effectiveness on the exterior bearings where surface corrosion is present (4 sq.ft CS4).

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
331	Re Conc Bridge Railing	3	12/03/2024	453.00	ft	313.00	115.00	25.00	0.00

The east railing has several spalls deeper than 1". The railings have moderate width vertical cracks and small spalls throughout.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
853	Utilities	3	12/03/2024	1.00	each	0.00	0.00	1.00	0.00

There is a deteriorated/broken utility conduit with exposed wires at the west end of Abutment 4. There are missing utility access covers in the railing near the NE, SE, and NW corners.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
857	Embankment Erosion	3	12/03/2024	1.00	each	0.00	0.00	1.00	0.00

NW embankment has a large erosion hole along the roadway shoulder just north of the bridge.

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
859	Vegetation	3	12/03/2024	1.00	each	0.00	0.00	1.00	0.00

Poison ivy is growing at the northeast corner, spreading along the exterior beam, and restricts inspection access. Trees and shrubs are also dense at each corner.



Bridge Inspection Report

056B00211N  
Inspector: Daniel Coulter  
Entered by: DCOULTER  
12/03/2024  
Standard (24 months)

ELEM NBR	ELEMENT NAME	ENV	INSP. DATE	QUANTITY	UNITS	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
860	Erosion Ctrl/Prt	3	12/03/2024	1.00	each	0.00	1.00	0.00	0.00

The Abutment 1 slope protection has a spall with 9" deep settlement at the top between Beams 5 & 6 and some undermining at the top at the east end. The Abutment 4 slope protection has cracks along the top.

# 056B00211N Routine Inspection 12/03/24



Looking north along I-65 NB toward Eastern Pkwy.



South bridge joint over Abutment 1 for NB traffic.



## 056B00211N Routine Inspection 12/03/24



East barrier has a few impact spalls.



North bridge joint over Abutment 4 for NB traffic.



# 056B00211N Routine Inspection 12/03/24



Looking south along I-65 NB toward I-264.



Looking north along I-65 SB toward Eastern Pkwy.





South bridge joint over Abutment 1 for SB traffic.



Close up





Typical barrier vertical cracking.



North bridge joint over Abutment 4 for SB traffic.



## 056B00211N Routine Inspection 12/03/24



Asphalt overlay has cracking in the SB right lane at the north bridge end.



Looking south along I-65 SB toward I-264.





NW embankment has a large erosion hole along the roadway shoulder.



East profile





Vertical clearance sign in place for WB traffic.



West profile





Vertical clearance sign in place for EB traffic.



Abutment 1





Abutment 1 spall with exposed rebar below Beam 3.



Abutment 1 has heavy debris on the cap, especially near the east end.





The underside of the deck adjacent to the Abutment 1 joint has spalling with exposed rebar, especially from Bays 15 through 17. Bay 15 shown.



Another view of last photo.



## 056B00211N Routine Inspection 12/03/24



Abutment 1 backwall has moderate to wide diagonal cracks at the ends.



Abutment 1 bearings have corrosion, many with section loss.





Several beam sole plates at Abutment 1 are not fully bearing on the rocker bearings and bang under live load. Beam 2 shown.



Some of the masonry plates at Abutment 1 no longer sit flush on the abutment seat due to extensive pack rust.





Abutment 1 bearings are over-expanded.



Beam 17 has distortion in the bottom flange near Abutment 1.





Large deck soffit spall with exposed rebar in Bay 13 of Span 1 near Pier 2.



South face of Pier 2.



Typical expanded Pier 2 bearings.



North face of Pier 2.





Span 2



Underside of the deck has several haunch spalls along the beam top flanges.



South face of Pier 3.



Pier 3 cap has a wide crack between Columns 1 and 2.





Pier 3-Column 9 spall.



North face of Pier 3.



Typical Pier 3 bearings.



Span 3





Abutment 4



Abutment 4 backwall has widespread patching with some large unsound areas and spalling with exposed rebar.





Abutment 4 moderate cracking with rust staining below the longitudinal joint.



Large area of unsound patching and spalling with exposed rebar in Bay 14 of Abutment 4.





Abutment 4 cap has wide horizontal cracks in the front face. Bay 15 shown.



Abutment 4 backwall wide vertical crack in Bay 19.





Close up of last photo.



Typical Abutment 4 bearing with corrosion.



Beam 1 at Abutment 4 with corrosion along the top flange.