

# APPENDIX D

## STRUCTURE INFORMATION

90 Inspection Date - 8/1/13

Inspector - ABUSH (194)

114B00005N - 8 Bridge ID

Standard - Primary Inspection Type

## Inspection Report with SI&A Data

Structure Description: 200 Foot - 3 Span Concrete continuous Tee Beam

2 District: 03 3 County: Warren 16 Latitude: 37°00'46.00" 7 Longitude: 86°22'46.00"

7 Facility Carried U.S. 31W

Milepoint: 17.780

6A Feature Intersected: SEABOARD RAILROAD

9 Location: .15 MI N.E. OF KY 446 NTR

NBI	X
Element	X
Fracture Critical	
Underwater	
Special	

### NBI CONDITION RATINGS

58 Deck:	7	61 Channel:	N
59 Superstructure:	7	62 Culvert:	N
60 Substructure:	7	Sufficiency Rating:	81

### DESIGN

Substandard:	No
Fracture Critical:	No
43A Main Span Material:	(2) Concrete Continuous
43B Main Span Design:	(04) Tee Beam
45 Number of Spans Main:	3
44A Approach Span Material:	Not Applicable
44B Approach Span Design:	Not Applicable
46 Number of Approach Spans:	0
107 Deck Type:	(1) Concrete-Cast-in-Place
108A Wearing Surface:	(4) Low Slump Concrete
108B Membrane:	(0) None
108C Deck Protection:	(0) None
Overlay Y/N:	Yes
Overlay Type:	PCC
Overlay Thickness:	1.300 in
Overlay Date:	

### APPRAISAL

36A Bridge Railings:	(0) Substandard
36B Transitions	(0) Substandard
36C Approach Guardrail:	(1) Meets Standards
36D Approach Guardrail Ends:	(1) Meets Standards
71 Waterway Adequacy:	(N) Not Applicable
72 Approach Alignment:	(8) Equal Desirable Crit
113 Scour Critical:	(N) Not over Waterway
Recommended Scour Critical:	(N) Not over Waterway

### LOAD RATINGS

63 Operating Type:	(2) Allowable Stress (AS)
64 Operating Rating:	36.0 tons
65 Inventory Type:	(2) Allowable Stress (AS)
66 Inventory Rating:	36.0 tons
Truck Capacity Type I:	43 tons
Truck Capacity Type II:	44 tons
Truck Capacity Type III:	47 tons
Truck Capacity Type IV:	59 tons

### GEOMETRIC DATA

48 Max Length Span:	80.000 ft
49 Structure Length:	200.000 ft
32 Approach Roadway:	51.837 ft
33 Median:	(2) Closed w/o Barrier
34 Skew:	40°
35 Flare:	No Flare
50A Curb/Sidewalk Width L:	5.249 ft
50B Curb/Sidewalk Width R:	5.249 ft
47 Horiz. Clearance:	56.499 ft
51 Width Curb to Curb:	53.999 ft
52 Width Out to Out:	64.501 ft

### ADMINISTRATIVE

27 Year Built:	1954
106 Year Reconstructed:	0
42A Type of Service On:	(1) Highway
42B Type of Service Under:	(2) Railroad
37 Historical Significance:	(5) Not Eligible
21 Custodian:	(01) State Hwy Agency
22 Owner:	(01) State Hwy Agency
101 Parallel Structure:	(N) No II Structure Exists

### CLEARANCES

10 Vert. Clearance:	99.999 ft
53 Min. Vert. Clearance Over:	99.999 ft
54A Vert. Under Reference:	(R) Railroad beneath struct.
54B Min. Vert. Underclearance:	23.501 ft
55A Lateral Under Reference:	(R) Railroad beneath struct.
55B Min. Lat. Underclearance R:	13.451 ft
56 Min. Lat. Underclearance L:	0.000 ft

### POSTINGS

41 Posting Status:	(A) Open, No Restriction
Signs Posted Cardinal:	No
Signs Posted Non-Cardinal:	No
Field Postings Gross:	-1 tons
Field Postings Type I:	-1 tons
Field Postings Type II:	-1 tons
Field Postings Type III:	-1 tons
Field Postings Type IV:	-1 tons

## Inspection Report with SI&A Data

### 16: Re Conc Top Flange

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	12,900.26	12,255.25	95%	645.01	5%	0	0%	0	0%

THERE IS MAP CRACKING AND EXPOSED AGGREGATE THROUGHOUT THE WEARING SURFACE. ALONG WITH SEVERAL LARGE AREAS OF DELAMINATION.

THERE IS A 20 FT. BY 2 FT. DELAMINATED AREA NEAR CENTER SPAN IN THE RIGHTHAND LANE NORTHBOUND.

SOUTH BOUND LEFT LANE 1 ft. X 2 ft. SPALL AROUND OLD PATCH IN SPAN #3 WITH A 2 ft. X 3 ft. DELAM JUST SOUTH OF THIS LOCATION

### 110: Re Conc Opn Girder/Beam

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	1,584	1,584	100%	0	0%	0	0%	0	0%

THERE ARE HAIRLINE STIRRUP CRACKS ON SOME BEAMS.

### 205: Re Conc Column

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	12	12	100%	0	0%	0	0%	0	0%

< none >

### 215: Re Conc Abutment

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	164	157	96%	6	4%	1	1%	0	0%

ABUTMENT #1 HAS 2 VERTICAL CRACKS

ABUTMENT #4 HAS 8 VERTICAL CRACKS WITH EFFLORESCENCE.

ABUTMENT #1 HAS A SPALL WITH STEEL EXPOSED.

THE SHEAR KEY AT ABUTMENT #1 BETWEEN BEAMS #2 AND #3 HAS A SPALL WITH STEEL EXPOSED.

## Inspection Report with SI&A Data

### 301: Pourable Joint Seal

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	64.5	57.5	89%	3	5%	0	0%	4	6%

THE SILICONE END JOINT AT ABUTMENT #1 NORTH BOUND SIDE HAS 14 ft. OF COMPLETE FAILURE.

### 303: Assem Jnt With Seal

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	64.5	64.5	100%	0	0%	0	0%	0	0%

< none >

### 310: Elastomeric Bearing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	8	8	100%	0	0%	0	0%	0	0%

THE MASONRY PLATES UNDER THE ELASTOMERIC BEARING PAD HAVE MODERATE SURFACE RUST.

### 311: Moveable Bearing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	16	16	100%	0	0%	0	0%	0	0%

< none >

### 313: Fixed Bearing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	8	8	100%	0	0%	0	0%	0	0%

< none >

## Inspection Report with SI&A Data

### 331: Re Conc Bridge Railing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	400	400	100%	0	0%	0	0%	0	0%

### 510: Wearing Surfaces

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	10,805.25	0	0%	10,805.25	100%	0	0%	0	0%

### 515: Steel Protective Coating

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	1	1	100%	0	0%	0	0%	0	0%

### 804: Sidewalk

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(LF)	600	600	100%	0	0%	0	0%	0	0%
1/3 OF THE QUANTITY REPRESENTS THE MEDIAN.									

### 851: Transitions

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%
POTHOLES IN THE ROADWAY AT BOTH ENDS OF THE BRIDGE AT THE TRANSITIONS									

## Inspection Report with SI&A Data

### 855: Debris on Super

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%

THERE IS DEBRIS ON ABUTMENT #4 AROUND THE ELASTOMERIC BEARING PADS.

### 857: Embankment Erosion

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%

WATER RUNOFF FROM THE ROADWAY IS FLOWING UNDER THE BRIDGE AT ABUTMENT #4 AND CREATING GULLYS THAT ARE WASHING AWAY THE SLOPE UNDER THE BRIDGE.

### 859: Vegetation

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%

THERE IS A SMALL AMOUNT OF VEGETATION IN SPAN #2 NEAR PIER #3 UNDER BEAMS #7 AND #8.

### 7358: DO NOT USE Concrete Cracking

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(SF)	10,800	10,260	95%	540	5%	0	0%	0	0%

THERE IS MAP CRACKING AND EXPOSED AGGREGATE THROUGHOUT THE WEARING SURFACE. ALONG WITH SEVERAL LARGE AREAS OF DELAMINATION.

THERE IS A 20 FT. BY 2 FT. DELAMINATED AREA NEAR CENTER SPAN IN THE RIGHTHAND LANE NORTHBOUND.

SOUTH BOUND LEFT LANE 1 ft. X 2 ft. SPALL AROUND OLD PATCH IN SPAN #3 WITH A 2 ft. X 3 ft. DELAM JUST SOUTH OF THIS LOCATION

## Inspection Report with SI&A Data

### 7359: DO NOT USE Concrete Efflorescenc

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(SF)	10.76	10.76	100%	0	0%	0	0%	0	0%

THERE IS MAP CRACKING AND EXPOSED AGGREGATE THROUGHTOUT THE WEARING SURFACE. ALONG WITH SEVERAL LARGE AREAS OF DELAMINATION.

THERE IS A 20 FT. BY 2 FT. DELAMINATED AREA NEAR CENTER SPAN IN THE RIGHTHAND LANE NORTHBOUND.

SOUTH BOUND LEFT LANE 1 ft. X 2 ft. SPALL AROUND OLD PATCH IN SPAN #3 WITH A 2 ft. X 3 ft. DELAM JUST SOUTH OF THIS LOCATION

### STRUCTURE NOTES

### INSPECTION NOTES

### WORK

Action: -1

Generated by abush on 08/01/2013

POTHoles IN THE ROADWAY AT BOTH ENDS OF THE BRIDGE AT THE TRANSITIONS

Action: -1

Generated by abush on 08/01/2013

THE SILICONE END JOINT AT ABUTMENT #1 NORTH BOUND SIDE HAS 14' OF COMPLETE FAILURE.

Action: -1

Generated by abush on 08/01/2013

WATER RUNOFF FROM THE ROADWAY IS FLOWING UNDER THE BRIDGE AT ABUTMENT #4 AND CREATING GULLYS THAT ARE WASHING AWAY THE SLOPE UNDER THE BRIDGE. COULD USE SOME PREVENTATIVE MAINTENANCE.

## Summary:

Inspection Date: 8/1/13  
 Inspector: ABUSH (194)  
 Primary Type: Standard (24 Months)

## Types of Inspections Performed:

National Bridge Inventory: Y  
 Element: Y  
 Fracture Critical: N  
 Underwater: N  
 Other Special: N

District Review Date: 8/27/13

Inspector Signature: \_\_\_\_\_

District Reviewer: **DSTEWART (37)**

## IDENTIFICATION

Bridge ID (8):	114B00005N	District Number:	3
Route Carried (7):	U.S. 31W	County (3):	114 Warren
Mile Point:	17.785	Feature Intersected (6):	SEABOARD RAILROAD
Location (9):	.15 MI N.E. OF KY 446 NTR	Road Name:	LOUISVILLE RD
Structure Description:	200 Foot - 3 Span Concrete continuous Tee Beam		

## NBI CONDITION

## SCHEDULE TAB

Deck (58):	7	Schedule:	Required (Y/N)	Last Date	Frequency	Next Date
Superstructure (59):	7	NBI (90):		8/1/13	(91): 24 mos	8/1/15
Substructure (60):	7	Fracture Critical (92A):	N	(93A): 1/1/01	(92A): mos	1/1/01
Culverts (62):	N	Underwater (92B):	N	(93B): 1/1/01	(92B): mos	1/1/01
Channel/Protection (61):	N	Other Special (92C):	N	(93C): 1/1/01	(92C): mos	1/1/01
		Elemental:	NA		24 mos	8/1/15

## Load Rating and Posting

## WATERWAY

Truck Type	Typ I	Typ II	Typ III	Typ IV	Gross	Scour Critical (113):	N
Recomm. Posting:	43	44	47	59		Observed 113 Rating:	N
Field Posting:	-1	-1	-1	-1	-1	Waterway Adeq. (71):	N
Posting Status (41):	A Open, no restriction						
Signs Posted:	Cardinal:	N	Non-Cardinal:	N			

## DECK/WEARING SURFACE

Deck Type (107):	1 Concrete-Cast-In-Place						
Wearing Surface/Protective System (108):	Type:	4	Membrane:	0	Protection:	0	
Traffic Safety Features (36):	Bridge Rail:	0	Transition:	0	Appr. Rail:	1	Rail Ends: 1
Overlay:	Y						
Overlay Type:	PCC	(34) Skew:	40				
Overlay Thickness:	1.3	(51) Curb-to-Curb Width:	54				

## Vertical Clearances

Minimum Vertical Overclearance (53):	99.99
Minimum Vertical Underclearance (54):	23.50
Maximum Vertical Clearance (10):	99.99
Minimum Vertical Clearance:	0.00

## Sufficiency Ratings

SR: 81 SD/FO: 0 Not Deficient

## Element Condition State Data

Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5
110/3	R/Conc Open Girder	LF	1584.00	1584.00	0.00	0.00	0.00	0.00
18/3	P Conc Deck/Thin Ovl	SF	10800.00	0.00	10800.00	0.00	0.00	0.00



## KYTC Bridge Inspection Report

## Summary:

Inspection Date: 8/1/13  
 Inspector: ABUSH (194)  
 Primary Type: Standard (24 Months)

## Types of Inspections Performed:

National Bridge Inventory: Y  
 Element: Y  
 Fracture Critical: N  
 Underwater: N  
 Other Special: N

## Element Condition State Data

Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5
205/3	R/Conc Column	EA	12.00	12.00	0.00	0.00	0.00	0.00
215/3	R/Conc Abutment	LF	164.00	157.00	6.00	1.00	0.00	0.00
301/3	Pourable Joint Seal	LF	64.50	57.50	3.00	4.00	0.00	0.00
303/3	Assembly Joint/Seal	LF	64.50	64.50	0.00	0.00	0.00	0.00
310/3	Elastomeric Bearing	EA	8.00	8.00	0.00	0.00	0.00	0.00
311/3	Moveable Bearing	EA	16.00	16.00	0.00	0.00	0.00	0.00
313/3	Fixed Bearing	EA	8.00	8.00	0.00	0.00	0.00	0.00
331/3	Conc Bridge Railing	LF	400.00	400.00	0.00	0.00	0.00	0.00
358/3	Deck Cracking SmFlag	EA	1.00	1.00	0.00	0.00	0.00	0.00
359/3	Soffit Smart Flag	EA	1.00	1.00	0.00	0.00	0.00	0.00
505/3	RC Sidewalk	LF	600.00	600.00	0.00	0.00	0.00	0.00
605/3	Transitions	EA	1.00	1.00	0.00	0.00	0.00	0.00
609/3	Debris on Superstruc	EA	1.00	1.00	0.00	0.00	0.00	0.00
611/3	Embankment Erosion	EA	1.00	1.00	0.00	0.00	0.00	0.00
613/3	Vegetation	EA	1.00	1.00	0.00	0.00	0.00	0.00

## Element Condition State Data

Str Unit	Elm/Env	Description	Description
1	110/3	R/Conc Open Girder	THERE ARE HAIRLINE STIRRUP CRACKS ON SOME BEAMS.
1	18/3	P Conc Deck/Thin Ovl	THERE IS MAP CRACKING AND EXPOSED AGGREGATE THROUGHTOUT THE WEARING SURFACE. ALONG WITH SEVERAL LARGE AREAS OF DELAMINATION.  THERE IS A 20 FT. BY 2 FT. DELAMINATED AREA NEAR CENTER SPAN IN THE RIGHTHAND LANE NORTHBOUND.  SOUTH BOUND LEFT LANE 1' X 2' SPALL AROUND OLD PATCH IN SPAN #3 WITH A 2' X 3' DELAM JUST SOUTH OF THIS LOCATION
1	205/3	R/Conc Column	
1	215/3	R/Conc Abutment	ABUTMENT #1 HAS 2 VERTICAL CRACKS  ABUTMENT #4 HAS 8 VERTICAL CRACKS WITH EFFLORESCENCE.  ABUTMENT #1 HAS A SPALL WITH STEEL EXPOSED.  THE SHEAR KEY AT ABUTMENT #1 BETWEEN BEAMS #2 AND #3 HAS A SPALL WITH STEEL EXPOSED.
1	301/3	Pourable Joint Seal	THE SILICONE END JOINT AT ABUTMENT #1 NORTH BOUND SIDE HAS 14' OF COMPLETE FAILURE.
1	303/3	Assembly Joint/Seal	
1	310/3	Elastomeric Bearing	THE MASONRY PLATES UNDER THE ELASTOMERIC BEARING PAD HAVE MODERATE SURFACE RUST.

Summary:  
Inspection Date: 8/1/13  
Inspector: ABUSH (194)  
Primary Type: Standard (24 Months)

Types of Inspections Performed:  
National Bridge Inventory: Y  
Element: Y  
Fracture Critical: N  
Underwater: N  
Other Special: N

Element Condition State Data				
Str	Unit	Elm/Env	Description	Description
1	311/3	Moveable Bearing		
1	313/3	Fixed Bearing		
1	331/3	Conc Bridge Railing		
1	358/3	Deck Cracking SmFlag	TRANSVERSE AND LONGITUDINAL CRACKING RANDOMLY THROUGHOUT ENTIRE DECK	
1	359/3	Soffit Smart Flag	THERE ARE FULL DEPTH CRACKS WITH EFFLORESCENCE IN THE DECK SOFFIT. A SPALL WITH EXPOSED STEEL WAS NOTED IN THE CURB SOFFIT, NEAR ABUTMENT #2 AND BEAM END #1.	
1	505/3	RC Sidewalk	1/3 OF THE QUANTITY REPRESENTS THE MEDIAN.	
1	605/3	Transitions	POTHOLES IN THE ROADWAY AT BOTH ENDS OF THE BRIDGE AT THE TRANSITIONS	
1	609/3	Debris on Superstruc	THERE IS DEBRIS ON ABUTMENT #4 AROUND THE ELASTOMERIC BEARING PADS.	
1	611/3	Embankment Erosion	WATER RUNOFF FROM THE ROADWAY IS FLOWING UNDER THE BRIDGE AT ABUTMENT #4 AND CREATING GULLYS THAT ARE WASHING AWAY THE SLOPE UNDER THE BRIDGE.	
1	613/3	Vegetation	THERE IS A SMALL AMOUNT OF VEGETATION IN SPAN #2 NEAR PIER #3 UNDER BEAMS #7 AND #8.	

Structure Notes

Inspection Notes

Work Candidates						
Inspector Candidates:						
Candidate ID:	Status	Priority	Assigned	Action	Elem	Date Recommended
A-KYTC-198CFF65-00000060	Approved	Medium	Unassigned	41	301	8/1/13
A-KYTC-198CFF65-00000064	Approved	High	Unassigned	41	605	8/1/13
A-KYTC-198CFF65-00000066	Approved	Medium	Unassigned	61	611	8/1/13

## Inspection Report with SI&A Data

**Structure Description:** 247 Foot - 4 Span Steel Stringer/Multi-beam or Girder

**2 District:** 03      **3 County:** Warren      **16 Latitude:** 37°00'38.00"      **7 Longitude:** 86°22'54.00"

**7 Facility Carried:** KY-446-10 NC Y

**Milepoint:** 0.190

**6A Feature Intersected:** US 31-W

**9 Location:** WB OVER US 31W NTRCHNGE

NBI	X
Element	X
Fracture Critical	
Underwater	
Special	

### NBI CONDITION RATINGS

<b>58 Deck:</b>	7	<b>61 Channel:</b>	N
<b>59 Superstructure:</b>	6	<b>62 Culvert:</b>	N
<b>60 Substructure:</b>	8	<b>Sufficiency Rating:</b>	79

### DESIGN

<b>Substandard:</b>	No
<b>Fracture Critical:</b>	Yes
<b>43A Main Span Material:</b>	(3) Steel
<b>43B Main Span Design:</b>	(02) Stringer / Girder
<b>45 Number of Spans Main:</b>	4
<b>44A Approach Span Material:</b>	Not Applicable
<b>44B Approach Span Design:</b>	Not Applicable
<b>46 Number of Approach Spans:</b>	0
<b>107 Deck Type:</b>	(1) Concrete-Cast-in-Place
<b>108A Wearing Surface:</b>	(3) Latex Concrete/Similar
<b>108B Membrane:</b>	(0) None
<b>108C Deck Protection:</b>	(0) None
<b>Overlay Y/N:</b>	Yes
<b>Overlay Type:</b>	Latex
<b>Overlay Thickness:</b>	1.500 in
<b>Overlay Date:</b>	

### APPRAISAL

<b>36A Bridge Railings:</b>	(0) Substandard
<b>36B Transitions</b>	(1) Meets Standards
<b>36C Approach Guardrail:</b>	(1) Meets Standards
<b>36D Approach Guardrail Ends:</b>	(1) Meets Standards
<b>71 Waterway Adequacy:</b>	(N) Not Applicable
<b>72 Approach Alignment:</b>	(8) Equal Desirable Crit
<b>113 Scour Critical:</b>	(N) Not over Waterway
<b>Recommended Scour Critical:</b>	(N) Not over Waterway

### LOAD RATINGS

<b>63 Operating Type:</b>	(2) Allowable Stress (AS)
<b>64 Operating Rating:</b>	110.0 tons
<b>65 Inventory Type:</b>	(2) Allowable Stress (AS)
<b>66 Inventory Rating:</b>	75.0 tons
<b>Truck Capacity Type I:</b>	50 tons
<b>Truck Capacity Type II:</b>	51 tons
<b>Truck Capacity Type III:</b>	54 tons
<b>Truck Capacity Type IV:</b>	65 tons

### GEOMETRIC DATA

<b>48 Max Length Span:</b>	67.999 ft
<b>49 Structure Length:</b>	247.001 ft
<b>32 Approach Roadway:</b>	23.950 ft
<b>33 Median:</b>	(0) No Median
<b>34 Skew:</b>	36°
<b>35 Flare:</b>	No Flare
<b>50A Curb/Sidewalk Width L:</b>	2.500 ft
<b>50B Curb/Sidewalk Width R:</b>	2.500 ft
<b>47 Horiz. Clearance:</b>	23.000 ft
<b>51 Width Curb to Curb:</b>	23.000 ft
<b>52 Width Out to Out:</b>	27.500 ft

### ADMINISTRATIVE

<b>27 Year Built:</b>	1965
<b>106 Year Reconstructed:</b>	0
<b>42A Type of Service On:</b>	(1) Highway
<b>42B Type of Service Under:</b>	(1) Highway
<b>37 Historical Significance:</b>	(5) Not Eligible
<b>21 Custodian:</b>	(01) State Hwy Agency
<b>22 Owner:</b>	(01) State Hwy Agency
<b>101 Parallel Structure:</b>	(N) No II Structure Exists

### CLEARANCES

<b>10 Vert. Clearance:</b>	99.999 ft
<b>53 Min. Vert. Clearance Over:</b>	99.999 ft
<b>54A Vert. Under Reference:</b>	(H) Hwy beneath struct.
<b>54B Min. Vert. Underclearance:</b>	15.499 ft
<b>55A Lateral Under Reference:</b>	(H) Hwy beneath struct.
<b>55B Min. Lat. Underclearance R:</b>	11.155 ft
<b>56 Min. Lat. Underclearance L:</b>	9.186 ft

### POSTINGS

<b>41 Posting Status:</b>	(A) Open, No Restriction
<b>Signs Posted Cardinal:</b>	No
<b>Signs Posted Non-Cardinal:</b>	No
<b>Field Postings Gross:</b>	-1 tons
<b>Field Postings Type I:</b>	-1 tons
<b>Field Postings Type II:</b>	-1 tons
<b>Field Postings Type III:</b>	-1 tons
<b>Field Postings Type IV:</b>	-1 tons

## Inspection Report with SI&A Data

### 12: Re Concrete Deck

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	6,792.54	6,792.54	100%	0	0%	0	0%	0	0%

OVERALL ROUGH FINISH WITH SOME CRACKING AND SHRINKAGE CRACKING, THROUGHOUT OVERLAY. THE OVERLAY WAS COMPLETED IN TWO POURS, ONE EACH ALONG THE LENGTH OF THE BRIDGE TO CENTERLINE - THE NORTH HALF OF THE OVERLAY EXHIBITS WORSE CRACKING WITH SOME MINOR SEPARATION.

### 107: Steel Opn Girder/Beam

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	980	0	0%	980	100%	0	0%	0	0%

PAINT SYSTEM IS FAILING OVER THE ENTIRE STRUCTURE DUE TO CRACKING AND POOR ADHESION.

THERE ARE FIVE LOCATIONS MARKED FOR CRACKED SPOT WELDS THAT CONNECT THE VERTICAL STIFFENER TO THE TOP FLANGE OF THE GIRDER IN A TENSION ZONE. THERE SHOULDN'T BE ANY WELDING AT THESE LOCATIONS. THESE WELDS HAVE CRACKED AND THE WELD HAS BROKEN ENTIRELY THROUGH. THE CRACK DID NOT PROPAGATE INTO THE BASE METAL AT ALL.

- GIRDER #2 SPAN #3 VERTICAL STIFFENER #1
- GIRDER #3 SPAN #2 VERTICAL STIFFENER #3
- GIRDER #1 SPAN #2 VERTICAL STIFFENER #1
- GIRDER #1 AND #2 AT THE VERTICAL STIFFENER OVER PIER #2

THE TOP OF GIRDERS #1 AND #4 AT ABUTMENT #1 ARE IN CONTACT WITH THE BACKWALL.

LOSS OF CAMBER IN BEAM #4 IN SPANS 1 AND 4.

### 205: Re Conc Column

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	6	5	83%	1	17%	0	0%	0	0%

SPALL IN COLUMN #2 IN PIER 2

## Inspection Report with SI&A Data

### 215: Re Conc Abutment

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	66	66	100%	0	0%	0	0%	0	0%
< none >									

### 234: Re Conc Pier Cap

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	90	90	100%	0	0%	0	0%	0	0%
< none >									

### 301: Pourable Joint Seal

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	27.5	27.5	100%	0	0%	0	0%	0	0%
THE SILICONE SEAL AT ABUTMENT #5 IS IN GOOD CONDITION.									

### 302: Compressn Joint Seal

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	27.5	27.5	100%	0	0%	0	0%	0	0%
THE JOINT AT ABUTMENT #1 IS FILLED WITH ROADWAY DEBRIS.									

## Inspection Report with SI&A Data

### 311: Moveable Bearing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	16	2	13%	14	88%	0	0%	0	0%

THE BEARING DEVICES AND THE END DIAPHRAGMS HAVE SOME RUSTING AND SECTION LOSS DUE TO LEAKAGE THROUGH THE PREVIOUSLY LOCATED SLIDING PLATE EXPANSION DEVICES (REPLACED 2001).

HEAVY RUSTING OF BEARIGN DEVICES AT ABUTMENT #1 WITH LOSS OF SECTION IN ANCHOR BOLTS.

### 313: Fixed Bearing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	4	4	100%	0	0%	0	0%	0	0%

< none >

### 333: Other Bridge Railing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	494	494	100%	0	0%	0	0%	0	0%

< none >

### 510: Wearing Surfaces

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	5,686.41	5,686.41	100%	0	0%	0	0%	0	0%

## Inspection Report with SI&A Data

### 515: Steel Protective Coating

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	1	1	100%	0	0%	0	0%	0	0%

### 803: Curb

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(LF)	494	494	100%	0	0%	0	0%	0	0%
< none >									

### 804: Sidewalk

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(LF)	494	494	100%	0	0%	0	0%	0	0%
< none >									

### 850: 2nd Elem

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%
THE DIAPHRAGMS AT THE WEST END OF THE BRIDGE, OVER ABUTMENT #1, ARE BADLY RUSTED WITH A 15% LOSS OF SECTION. THE RUSTING WAS CAUSED BY WATER LEAKAGE THROUGH THE OLD SLIDING PLATE EXPANSION DAM. 100% SECTION LOSS IN WEB AND LOWER FLANGE OF DIAPHRAGM #1 OVER ABUTMENT #1.									

## Inspection Report with SI&A Data

### 860: Erosion Ctrl/Prt

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%

ROADWAY RUNOFF UNDER THE CONCRETE SLOPE PROTECTION HAS CAUSED THE BOTTOM SLABS OF THE SLOPE PROTECTION TO SETTLE.

### 7356: DO NOT USE Steel Cracking/Fatigue

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	1	100%	0	0%	0	0%	0	0%

SEE NOTE IN ELEMENT #107 FOR FIVE (5) LOCATIONS OF CRACKED WELDS.

### 7362: DO NOT USE Superstruct Traf Impt

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	1	100%	0	0%	0	0%	0	0%

HIGH LOAD IMPACT DAMAGE TO THE LOWER FLANGE OF GIRDER #2 IN SPAN #3. GIRDERS #1, #3, AND #4 ALSO HAVE MINOR SURFACE DAMAGE FROM THE SAME HIGH LOAD.

IMPACT DAMAGE TO THE LOWER WEB IN GIRDER #1 IN SPAN #2 NEAR MIDSPAN

### STRUCTURE NOTES

### INSPECTION NOTES

### WORK

Action:



Summary:  
Inspection Date: 8/5/13  
Inspector: RSEMAR (193)  
Primary Type: Standard (24 Months)

Types of Inspections Performed:  
National Bridge Inventory: Y  
Element: Y  
Fracture Critical: N  
Underwater: N  
Other Special: N

District Review Date: 8/27/13

Inspector Signature: \_\_\_\_\_

District Reviewer: DSTEWARD (37)

IDENTIFICATION			
Bridge ID (8):	114B00034N	District Number:	3
Route Carried (7):	KY-446-10 NC Y	County (3):	114 Warren
Mile Point:	0.190	Feature Intersected (6):	US 31-W
Location (9):	WB OVER US 31W NTRCHNGE	Road Name:	INTERSTATE DR NC
Structure Description:	247 Foot - 4 Span Steel Stringer/Multi-beam or Girder		

NBI CONDITION		SCHEDULE TAB				
Deck (58):	7	Schedule:	Required (Y/N)	Last Date	Frequency	Next Date
Superstructure (59):	6	NBI (90):		8/5/13	(91): 24 mos	8/5/15
Substructure (60):	8	Fracture Critical (92A):	N	(93A): 1/1/01	(92A): mos	1/1/01
Culverts (62):	N	Underwater (92B):	N	(93B): 1/1/01	(92B): mos	1/1/01
Channel/Protection (61):	N	Other Special (92C):	N	(93C): 1/1/01	(92C): mos	1/1/01
		Elemental:	NA		24 mos	8/5/15

Load Rating and Posting						WATERWAY	
Truck Type	Typ I	Typ II	Typ III	Typ IV	Gross	Scour Critical (113):	N
Recomm. Posting:	50	51	54	65		Observed 113 Rating:	N
Field Posting:	-1	-1	-1	-1	-1	Waterway Adeq. (71):	N
Posting Status (41):	A Open, no restriction						
Signs Posted:	Cardinal:	N	Non-Cardinal:	N			

DECK/WEARING SURFACE							
Deck Type (107):	1 Concrete-Cast-In-Place						
Wearing Surface/Protective System (108):	Type:	3	Membrane:	0	Protection:	0	
Traffic Safety Features (36):	Bridge Rail:	0	Transition:	1	Appr. Rail:	1	Rail Ends: 1
Overlay:	Y						
Overlay Type:	Latex	(34) Skew:	36				
Overlay Thickness:	1.5	(51) Curb-to-Curb Width:	23				

Vertical Clearances	
Minimum Vertical Overclearance (53):	99.99
Minimum Vertical Underclearance (54):	15.49
Maximum Vertical Clearance (10):	99.99
Minimum Vertical Clearance:	0.00

Sufficiency Ratings	
SR:	79
SD/FO:	2 Functionally Obsolete

Element Condition State Data									
Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5	
107/3	Paint Stl Opn Girder	LF	980.00	0.00	980.00	0.00	0.00	0.00	
18/3	P Conc Deck/Thin Ovl	SF	5557.50	5557.50	0.00	0.00	0.00	0.00	

## KYTC Bridge Inspection Report

## Summary:

Inspection Date: 8/5/13  
 Inspector: RSEMAR (193)  
 Primary Type: Standard (24 Months)

## Types of Inspections Performed:

National Bridge Inventory: Y  
 Element: Y  
 Fracture Critical: N  
 Underwater: N  
 Other Special: N

## Element Condition State Data

Elm/Env	Description	Units	Total QTY	QTY CS1	QTY CS2	QTY CS3	QTY CS4	QTY CS5
205/3	R/Conc Column	EA	6.00	5.00	1.00	0.00	0.00	0.00
215/3	R/Conc Abutment	LF	66.00	66.00	0.00	0.00	0.00	0.00
234/3	R/Conc Cap	LF	90.00	90.00	0.00	0.00	0.00	0.00
301/3	Pourable Joint Seal	LF	27.50	27.50	0.00	0.00	0.00	0.00
302/3	Compressn Joint Seal	LF	27.50	27.50	0.00	0.00	0.00	0.00
311/3	Moveable Bearing	EA	16.00	2.00	14.00	0.00	0.00	0.00
313/3	Fixed Bearing	EA	4.00	4.00	0.00	0.00	0.00	0.00
333/3	Other Bridge Railing	LF	494.00	494.00	0.00	0.00	0.00	0.00
356/3	Steel Fatigue SmFlag	EA	1.00	1.00	0.00	0.00	0.00	0.00
362/3	Traf Impact SmFlag	EA	1.00	1.00	0.00	0.00	0.00	0.00
503/3	Curbs	LF	494.00	494.00	0.00	0.00	0.00	0.00
505/3	RC Sidewalk	LF	494.00	494.00	0.00	0.00	0.00	0.00
601/3	MisAlign/ot of plane	EA	1.00	1.00	0.00	0.00	0.00	0.00
604/3	2nd Elem Dist	EA	1.00	1.00	0.00	0.00	0.00	0.00
614/3	Eros Contr	EA	1.00	1.00	0.00	0.00	0.00	0.00

## Element Condition State Data

Str	Unit	Elm/Env	Description	Description
1	107/3	Paint Stl Opn Girder	PAINT SYSTEM IS FAILING OVER THE ENTIRE STRUCTURE DUE TO CRACKING AND POOR ADHESION.	<p>THERE ARE FIVE LOCATIONS MARKED FOR CRACKED SPOT WELDS THAT CONNECT THE VERTICAL STIFFENER TO THE TOP FLANGE OF THE GIRDER IN A TENSION ZONE. THERE SHOULDN'T BE ANY WELDING AT THESE LOCATIONS. THESE WELDS HAVE CRACKED AND THE WELD HAS BROKEN ENTIRELY THROUGH. THE CRACK DID NOT PROPAGATE INTO THE BASE METAL AT ALL.</p> <p>-GIRDER #2 SPAN #3 VERTICAL STIFFENER #1          -GIRDER #3 SPAN #2 VERTICAL STIFFENER #3          -GIRDER #1 SPAN #2 VERTICAL STIFFENER #1          -GIRDER #1 AND #2 AT THE VERTICAL STIFFENER OVER PIER #2</p> <p>THE TOP OF GIRDERS #1 AND #4 AT ABUTMENT #1 ARE IN CONTACT WITH THE BACKWALL.</p> <p>LOSS OF CAMBER IN BEAM #4 IN SPANS 1 AND 4.</p>
1	18/3	P Conc Deck/Thin Ovl	OVERALL ROUGH FINISH WITH SOME CRACKING AND SHRINKAGE CRACKING, THROUGHOUT OVERLAY. THE OVERLAY WAS COMPLETED IN TWO POURS, ONE EACH ALONG THE LENGTH OF THE BRIDGE TO CENTERLINE - THE NORTH HALF OF THE OVERLAY EXHIBITS WORSE CRACKING WITH SOME MINOR SEPARATION.	
1	205/3	R/Conc Column	SPALL IN COLUMN #2 IN PIER 2	
1	215/3	R/Conc Abutment		
1	234/3	R/Conc Cap		
1	301/3	Pourable Joint Seal	THE SILICONE SEAL AT ABUTMENT #5 IS IN GOOD CONDITION.	

## Summary:

Inspection Date: 8/5/13  
 Inspector: RSEMAR (193)  
 Primary Type: Standard (24 Months)

## Types of Inspections Performed:

National Bridge Inventory: Y  
 Element: Y  
 Fracture Critical: N  
 Underwater: N  
 Other Special: N

## Element Condition State Data

Str	Unit	Elm/Env	Description	Description
1	302/3	Compressn Joint Seal		THE JOINT AT ABUTMENT #1 IS FILLED WITH ROADWAY DEBRIS.
1	311/3	Moveable Bearing		THE BEARING DEVICES AND THE END DIAPHRAGMS HAVE SOME RUSTING AND SECTION LOSS DUE TO LEAKAGE THROUGH THE PREVIOUSLY LOCATED SLIDING PLATE EXPANSION DEVICES (REPLACED 2001).  HEAVY RUSTING OF BEARIGN DEVICES AT ABUTMENT #1 WITH LOSS OF SECTION IN ANCHOR BOLTS.
1	313/3	Fixed Bearing		
1	333/3	Other Bridge Railing		
1	356/3	Steel Fatigue SmFlag		SEE NOTE IN ELEMENT #107 FOR FIVE (5) LOCATIONS OF CRACKED WELDS.
1	362/3	Traf Impact SmFlag		HIGH LOAD IMPACT DAMAGE TO THE LOWER FLANGE OF GIRDER #2 IN SPAN #3. GIRDERS #1, #3, AND #4 ALSO HAVE MINOR SURFACE DAMAGE FROM THE SAME HIGH LOAD.  IMPACT DAMAGE TO THE LOWER WEB IN GIRDER #1 IN SPAN #2 NEAR MIDSPAN
1	503/3	Curbs		
1	505/3	RC Sidewalk		
1	601/3	MisAlign/ot of plane		LOSS OF CAMBER IN BEAM #4 IN SPANS 1 AND 4.  GIRDER #3 IN SPAN #1 JUST WEST OF THE SPLICE PLATE THE LOWER FLANGE IS SLIGHTLY BENT OUT OF PLANE.  GIRDER #2 IN SPAN #1 BETWEEN PIER #2 AND THE SPLICE PLATE THE LOWER FLANGE IS BENT SLIGHTLY OUT OF PLANE
1	604/3	2nd Elem Dist		THE DIAPHRAGMS AT THE WEST END OF THE BRIDGE, OVER ABUTMENT #1, ARE BADLY RUSTED WITH A 15% LOSS OF SECTION. THE RUSTING WAS CAUSED BY WATER LEAKAGE THROUGH THE OLD SLIDING PLATE EXPANSION DAM. 100% SECTION LOSS IN WEB AND LOWER FLANGE OF DIAPHRAGM #1 OVER ABUTMENT #1.
1	614/3	Eros Contr		ROADWAY RUNOFF UNDER THE CONCRETE SLOPE PROTECTION HAS CAUSED THE BOTTOM SLABS OF THE SLOPE PROTECTION TO SETTLE.

## Structure Notes

## Inspection Notes

## Work Candidates

## Inspector Candidates:

Candidate ID:	Status	Priority	Assigned	Action	Elem	Date Recommended
A-KYTC-15CEA849-0000001F	Approved	High	Unassigned	33	311	8/5/13

## Inspection Report with SI&A Data

**Structure Description:** 29.5 Foot - Single Span Steel Stringer/Multi-beam or Girder

**2 District:** 03      **3 County:** Warren      **16 Latitude:** 37°00'42.00"      **7 Longitude:** 86°23'24.00"

**7 Facility Carried:** CXS RAILROAD

**Milepoint:** 0.080

**6A Feature Intersected:** PLUM SPRINGS LOOP

**9 Location:** 400 FT. N. JCT US 31W

NBI	X
Element	X
Fracture Critical	
Underwater	
Special	

### NBI CONDITION RATINGS

<b>58 Deck:</b>	N	<b>61 Channel:</b>	N
<b>59 Superstructure:</b>	7	<b>62 Culvert:</b>	N
<b>60 Substructure:</b>	6	<b>Sufficiency Rating:</b>	-2

### DESIGN

<b>Substandard:</b>	No
<b>Fracture Critical:</b>	No FC Details
<b>43A Main Span Material:</b>	(3) Steel
<b>43B Main Span Design:</b>	(02) Stringer / Girder
<b>45 Number of Spans Main:</b>	1
<b>44A Approach Span Material:</b>	Not Applicable
<b>44B Approach Span Design:</b>	Not Applicable
<b>46 Number of Approach Spans:</b>	0
<b>107 Deck Type:</b>	N/A (NBI)
<b>108A Wearing Surface:</b>	(N) N/A no deck (NBI)
<b>108B Membrane:</b>	(N) N/A no deck (NBI)
<b>108C Deck Protection:</b>	(N) N/A no deck (NBI)
<b>Overlay Y/N:</b>	No
<b>Overlay Type:</b>	None
<b>Overlay Thickness:</b>	0.000 in
<b>Overlay Date:</b>	

### APPRAISAL

<b>36A Bridge Railings:</b>	(0) Substandard
<b>36B Transitions</b>	(0) Substandard
<b>36C Approach Guardrail:</b>	(0) Substandard
<b>36D Approach Guardrail Ends:</b>	(0) Substandard
<b>71 Waterway Adequacy:</b>	(N) Not Applicable
<b>72 Approach Alignment:</b>	(5) Abover Tolerable
<b>113 Scour Critical:</b>	(N) Not over Waterway
<b>Recommended Scour Critical:</b>	(N) Not over Waterway

### LOAD RATINGS

<b>63 Operating Type:</b>	(5) No rating analysis performed
<b>64 Operating Rating:</b>	-1.1 tons
<b>65 Inventory Type:</b>	(5) No rating analysis performed
<b>66 Inventory Rating:</b>	-1.1 tons
<b>Truck Capacity Type I:</b>	tons
<b>Truck Capacity Type II:</b>	tons
<b>Truck Capacity Type III:</b>	tons
<b>Truck Capacity Type IV:</b>	tons

### GEOMETRIC DATA

<b>48 Max Length Span:</b>	27.500 ft
<b>49 Structure Length:</b>	29.501 ft
<b>32 Approach Roadway:</b>	27.001 ft
<b>33 Median:</b>	(0) No Median
<b>34 Skew:</b>	0°
<b>35 Flare:</b>	No Flare
<b>50A Curb/Sidewalk Width L:</b>	0.000 ft
<b>50B Curb/Sidewalk Width R:</b>	0.000 ft
<b>47 Horiz. Clearance:</b>	18.999 ft
<b>51 Width Curb to Curb:</b>	17.000 ft
<b>52 Width Out to Out:</b>	0.000 ft

### ADMINISTRATIVE

<b>27 Year Built:</b>	1925
<b>106 Year Reconstructed:</b>	0
<b>42A Type of Service On:</b>	(2) Railroad
<b>42B Type of Service Under:</b>	(1) Highway
<b>37 Historical Significance:</b>	(5) Not Eligible
<b>21 Maintenance Responsibility:</b>	(27) Railroad
<b>22 Owner:</b>	(27) Railroad
<b>101 Parallel Structure:</b>	(N) No II Structure Exists

### CLEARANCES

<b>10 Vert. Clearance:</b>	14.800 ft
<b>53 Min. Vert. Clearance Over:</b>	99.999 ft
<b>54A Vert. Under Reference:</b>	(H) Hwy beneath struct.
<b>54B Min. Vert. Underclearance:</b>	14.800 ft
<b>55A Lateral Under Reference:</b>	(H) Hwy beneath struct.
<b>55B Min. Lat. Underclearance R:</b>	1.001 ft
<b>56 Min. Lat. Underclearance L:</b>	0.000 ft

### POSTINGS

<b>41 Posting Status:</b>	(A) Open, No Restriction
<b>Signs Posted Cardinal:</b>	No
<b>Signs Posted Non-Cardinal:</b>	No
<b>Field Postings Gross:</b>	-1 tons
<b>Field Postings Type I:</b>	-1 tons
<b>Field Postings Type II:</b>	-1 tons
<b>Field Postings Type III:</b>	-1 tons
<b>Field Postings Type IV:</b>	-1 tons

## Inspection Report with SI&A Data

107: Steel Opn Girder/Beam									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	118	106	90%	12	10%	0	0%	0	0%
<p>BEAM #1 HAS IMPACT DAMAGE AT MIDSPAN, ON THE LOWER FLANGE/BUILT UP PLATE.</p> <p>THERE ARE LOCATIONS THAT HAVE MINOR SURFACE RUSTING.</p>									

515: Steel Protective Coating									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	0.3	0.3	100%	0	0%	0	0%	0	0%

217: Masonry Abutment									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	106	0	0%	81	76%	25	24%	0	0%
<p>THERE IS SOME DETERIORATION OF THE MORTAR BETWEEN SEVERAL STONES IN EACH ABUTMENT . THERE ARE ALSO SOME RANDOMLY LOCATED MINOR CRACKS AND SLIGHT DETERIORATION AMONG SOME STONES.</p> <p>THERE IS A FULL-DEPTH CRACK IN THE SECOND STONE BACK FROM THE NW WINGWALL. A FULL-DEPTH CRACK WAS ALSO NOTED IN THE THIRD STONE BACK FROM THE TOE OF NE WING-BREAK, THIRD COARSE ABOVE GROUND LEVEL.</p> <p>THE ENTIRE SECOND COARSE OF STONES IN THE NE WING AND ONE STONE OF THE NW WING, NEAR GROUND LINE, ARE SHOWING MODERATE AMOUNTS OF DETERIORATION AND SECTION LOSS.</p>									

234: Re Conc Pier Cap									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	106	105	99%	0	0%	1	1%	0	0%
<p>THE CONCRETE BEARING PEDESTAL ON ABUTMENT #2 UNDER THE BEARING DEVICE FOR BEAM #1, HAS A LARGE SPALL &amp; SOME CRACKING.</p> <p>THERE IS A SMALL SPALL IN THE LOWER PORTION OF THE CONCRETE BEARING PEDESTAL FACE ON ABUTMENT #1.</p>									

## Inspection Report with SI&A Data

311: Moveable Bearing									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	8	7	88%	1	13%	0	0%	0	0%
SLIDING STEEL PLATE BEARING DEVICES WERE ADDED BETWEEN THE SOLE PLATE AND THE CONCRETE BEARING PEDESTAL UNDER ALL GIRDERS, @ EACH END, IN 1997.									

515: Steel Protective Coating									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
EACH	0.09	0.09	100%	0	0%	0	0%	0	0%

800: Culv Wingwall									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(LF)	47	27	57%	7	15%	13	28%	0	0%
47 ft. TOTAL FEET: 27 ft. OF WHICH IS CONCRETE AND 20 ft. OF WHICH IS STONE. 13 ft. OF STONE IS IN CONDITION STATE 3: 3 ft. AT SOUTH EAST AND 10 FEET AT NORTH WEST. CONCRETE PORTION HAS NO PROBLEMS. 7 ft. OF STONE IN CONDITION STATE 2.									

859: Vegetation									
Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%
VINES GROWING ON THE SOUTH WEST WING WALL									

## Inspection Report with SI&A Data

**7360: DO NOT USE Settlement**

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
(EA)	1	0	0%	1	100%	0	0%	0	0%

THE NW WINGWALL IS SEPARATED FROM ABUTMENT #1 APPROXIMATELY 2 3/4 in. AT THE TOP AND APPROXIMATELY 1 in. AT THE BOTTOM (SEE PHOTOS) WATCH CLOSELY ON EACH INSPECTION.

**STRUCTURE NOTES****INSPECTION NOTES****WORK**

**Action:** -1 - Converted Work Candidates

Generated by abush on 02/06/2014

VINES GROWING ON THE SOUTH WEST WING WALL NEED TO BE REMOVED.