

APPENDIX C

RECURRING MAINTENANCE ISSUES

Location 9 (2): KY 377 MP 2.50 to MP 2.70



Slope/shoulder stability issues adjacent to the roadway at Buck Crawford Place at Indian Creek. 5/20/2015

Location 9: KY 377 MP 2.50 to MP 2.70



Slope/shoulder stability issues adjacent to the roadway at Buck Crawford Place at Indian Creek. 5/20/2015

Location 8: KY 59 MP 3.40 to MP 3.45



Slope/shoulder stability issues adjacent to the roadway at Mike Thomas Place at Indian Creek.

Location 7 (2) : KY 377 MP 4.45 to MP 4.50



Slope/shoulder stability issues adjacent to the roadway near Eddie Stamm Farm at Indian Creek.

Location 7: KY 377 MP 4.45 to MP 4.50



Slope/shoulder stability issues adjacent to the roadway near Eddie Stamm Farm at Indian Creek. 5/29/2015

Location 6: KY 377 MP 7.15 to MP 7.35



Slope/shoulder stability issues adjacent to the roadway at Indian Creek. 5/29/2015

Location 5: KY 344 / KY 377 Intersection



Occasional flooding of the intersection requires KYTC maintenance crews to close the road until water recedes.

Location 4: KY 344 MP 14.30 to MP 14.40



Slope/shoulder stability issues adjacent to the roadway near Bob Thurman Curve at Kinniconick Creek.

Location 3: KY 344 MP 15.70 to MP 15.90



Slope/shoulder stability issues adjacent to the roadway near “Beaver Pond” at Kinniconick Creek.

Location 2: KY 344 MP 18.10 to MP 18.20



Issues adjacent to the roadway near the Kinniconick Hotel at Kinniconick Creek.

Location 1: KY 59 MP 21.8 to MP 23.50



Along the west slope of Vanceburg Hill, there are more problems with the uphill side falling into KY 59 than with the downhill side falling away from KY 59.