

ORD Support Log

Issue	Solution/Comment	Version	Date Reported	Priority	Date Fixed	Fixed By:
Need a workflow for writing deeds	write a workflow for writing deeds	10.07.03.18	1/24/2020	Med	5/29/2020	BPS
Create Right of way Workflows for Existing and Proposed	Created Right of Way Workflows for Existing and Proposed.	10.08.01.33	5/7/2020	Med	5/29/2020	BPS
Dimension Styles for annotation with arrow terminator too large	change terminator size to width of 50 and height of 25	10.08.01.33	5/29/2020	Med	5/29/2020	BPS
Sheet Model text fields do not update unless they are activated and opened. Workset properties will not update if there is a change as well.	Wrote VBA to auto update those sheets and placed it on the KYTC - Roadway Tab in ORD	10.08.01.33	6/1/2020	High	6/3/2020	ADM
Need a process to automate annotation and reporting of Lat Lon	A VBA called SONEZLL has been created and added to the workspace called SONEZLL_Annotation stands for Station, Offset, Northing Easting, Z, Lat Lon. Along with the appropriate reports to allow it to run, Along with a custom button Called Lat Lon. VBAs also have a read me file with the same name that explain setup and use.	10.08.01.33	6/2/2020	Med	6/4/2020	BPS/Bentley
XML reports not showing up we get Bentley or KYTC but not both	Two things needed to be changed. KYTC_Standards_OC.cfg Comment out #if exists (\$(CIVIL_ORGANIZATION_STANDARDS)Reports/*.xml) Change Path of the Civil_reports_Directory to = \$(civil_Organization_Standards)Reports/KYTC/ Comment out #endif Copy all Bentley reports to the KYTC reports location	10.08.01.33	6/4/2020	Med	6/4/2020	BPS/ADM/MAS
Cross Sections do not auto annotate the drawing scale on the sheet.	Fixed the Cross Section Sheet Seeds to auto-annotate drawing scale	10.08.01.33	6/1/2020	Med	6/4/2020	ADM
Despite changing the feature definition for the mesh "PR Bridge" volume setting to "none", ORD was filling under the bridge.	The component in the Template Libraries provided had the barrier wall in the railings set to "Barrier Wall" instead of "Bridge" as the feature definition. This has now been changed.	10.08.01.33	6/5/2020	Med	6/8/2020	EKS
Survey feature Guardrail Set to Breakline needs to be set to Do not triangle	Changed Guardrail to Do Not Triangulate	10.08.01.33	6/16/2020	High	6/17/2020	BPS
LT and RT "V" Ditch not showing in the design model	Set Show Template Graphics to True for LT and RT V Ditch	10.08.01.33	6/26/2020	High	6/26/2020	ADM
Missing Element Template for Survey	Create Element Template EX_Underground Fiber Optic	10.08.01.33	7/6/2020	High	7/6/2020	BPS
No shoulder on some Templates - 4 lane with median	Point names were duplicated on the LT and RT SHLD	10.08.00.88	4/17/2020	High	7/8/2020	BPS
Element Templates are not set up to use Text Styles	Assign Text Styles to all Roadway Element Templates	10.08.01.33	7/15/2020	High	7/21/2020	BPS
CADD Standards Level Charts for Roadway Does not include Text Styles	Assign Text Styles to Roadway Levels_Presentation.xls	10.08.01.33	7/21/2020	High	7/24/2020	BPS
ROW Summary Tab in the KYTC Summaries Excel file for delivery was missing information that is usually present outside the table at the bottom on the ROW Summary sheet. This information includes the code list of what type of building, sewer system and other details about the parcel.	This information was added to the bottom of the chart, and the print selection was also updated.	10.08.01.33	7/21/2020	Med	7/31/2020	EKS
Example Box Beam Bridge template had too many beams.	Cleaned up the template in the delivered template library.	10.08.01.33	7/21/2020	Low	7/31/2020	EKS
KYTC Sheet Directory Sheets have been placed outside of the sheet boundary.	Fixed Sheet Seeds by moving the references to the correct cutline.	10.08.01.33	8/3/2020	Low	8/3/2020	ADM
KYTC Sheet Directory Sheets sheet numbering not indexed correctly	Fixed Sheet Seeds indexing data field with correct model properties	10.08.01.33	8/3/2020	Low	8/3/2020	ADM
Model Annotations bringing in Element Annotations when used, creating double text	Fixed with R2 2020 Priority Build	10.08.01.33	5/6/2020	Critical	8/1/2020	Bentley
KYTC Linestyles showing GR for PropertyLine	LineStyle Fixed with correct components for GR and EX Property Lines	10.08.02.05	8/24/2020	Low	8/24/2020	ADM