



SECTION THROUGH END BENT CAP AND BEAM END

PREVENTIVE MAINTENANCE

Note: Top and face of cap the entire length including cap ends and front face of end bent back wall shall be cleaned and have concrete coating applied as specified within the limits shown. Apply rust inhibitor to beams and lubricate bearings as specified.

BRIDGE NO.
056B00196N

Note: See Special Notes

Commonwealth of Kentucky DEPARTMENT OF HIGHWAYS	
COUNTY JEFFERSON	
PREPARED BY <i>PREVENTIVE MAINTENANCE</i>	
HMB PROFESSIONAL ENGINEERS	