

## **APPENDIX B**

### **PHOTO LOG**

---

# SECTION 1

## APPENDIX B PHOTO LOG



1) Old Madison Pike at KY 17



2) Hillside in corridor of Alternative 1.1



3) KY 17 Bridge over Banklick Creek



4) Old Madison Pike Culvert over  
Wayman Branch



5) Reconstructed Section of KY 1501 at  
KY 17



6) KY 17 looking south toward the KY  
1501 intersection



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



7) Commercial Building at western end of KY 1501, near KY 17



8) KY 17 looking north toward the KY 1501 intersection



9) Historic Site at KY 1501 and KY 17 intersection



10) Historic Site located along Madison Pike



11) KY 1501, looking east where the reconstructed Section of KY 1501 transitions to the original alignment



12) KY 1501, historic sites located west of Wayman Branch



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



13) Wayman Branch Road at KY 1501



14) KY 1501 at Wayman Branch Road



15) KY 1501, Utility Substation located west of Wayman Branch Road



16) KY 1501, Hands Pike Hill looking east



17) KY 1501, curve at the bottom of Hands Pike Hill, looking west



18) Wayman Branch



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



19) Wayman Branch



20) KY 1501 over Wayman Branch  
looking east



21) KY 1501 culvert over Wayman Branch



22) KY 1501 over Wayman Branch  
looking west



23) KY 1501 looking east at the bottom of  
Hands Pike Hill



24) KY 1501, Hands Pike looking east



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



25) KY 1501, Hands Pike Hill looking east



26) KY 1501, Hands Pike Hill looking east



27) KY 1501, Hands Pike Hill looking east



28) KY 1501, Hands Pike Hill looking east



29) KY 1501, Hands Pike Hill looking east



30) KY 1501, Hands Pike Hill looking west



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



31) KY 1501, Hands Pike Hill Curve looking west



32) KY 1501, Hands Pike Hill looking east



33) KY 1501, looking east near the top of Hands Pike Hill



34) KY 1501, Hands Pike Hill looking west; Hill on right side is proposed to be removed with Spot Improvement 1



35) KY 1501, Hands Pike Hill looking west at substandard drainage



36) KY 1501, Hands Pike Hill looking west at cross drain



# SECTION 1 (continued)

## APPENDIX B PHOTO LOG



37) KY 1501, looking west from near the top of Hands Pike Hill



38) KY 1501, looking east from near the top of Hands Pike Hill



# SECTION 2

## APPENDIX B PHOTO LOG



1) KY 1501, looking east towards the Fire Station



2) KY 1501, Hands Pike at Tripoli Lane



3) KY 1501, Hands Pike looking east at utility boxes



4) KY 1501, looking west from the Fire Station



5) KY 1501, looking west at playground near the Fire Station



6) KY 1501, looking west at playground at the Fire Station



## SECTION 2 (continued)

## APPENDIX B PHOTO LOG



7) KY 1501, looking east from Tripoli Lane



8) KY 1501, looking east from Tripoli Lane



9) KY 1501, looking east



10) KY 1501, looking east



11) KY 1501, looking west



12) KY 1501, looking east



## SECTION 2 (continued)

## APPENDIX B PHOTO LOG



13) KY 1501, looking east



14) KY 1501, looking east towards  
Section 3



15) Residential neighborhood off Section  
2



16) KY 1501, looking east towards  
Section 3



17) KY 1501 looking west



18) Residential homes along KY 1501,  
near Crystal Lake Drive



# SECTION 3

## APPENDIX B PHOTO LOG



1) KY 1501, looking west



2) KY 1501, looking east



3) KY 1501, looking west



4) KY 1501, looking east



5) KY 1501, looking west



# SECTION 4

## APPENDIX B PHOTO LOG



1) KY 1501, looking west



2) KY 1501, looking east



3) KY 1501, looking east



4) KY 1501, looking west



5) KY 16 at KY 1501 looking north



6) KY 16 at KY 1501 looking south