



# BASE FAILURE REPAIR DETAILS

## BASE FAILURE CROSS SECTION DETAIL




\* For Base Failure Repair locations within the limits of Resurfacing/Overlay Sections # 1 & 2, Overlay the Base Failure Repair with 1.25" Asph Surf. according to the Special Notes.  
For Base Failure Repair locations outside of the Resurfacing Limits, Mill & Inlay 1.25" Asph Surf according to the "Profile" and "Top View" details below, and according to the Special Notes.

## BASE FAILURE PROFILE DETAIL



## BASE FAILURE TOP VIEW DETAIL



FOR MORE INFORMATION, REFER TO THE "SPECIAL NOTE FOR BASE FAILURE REPAIR"

- ① "BASE FAILURE" locations are listed elsewhere in the proposal. The Engineer shall make the final determination as to the width, depth, and length, and the exact location of each base failure.

Once work has begun, the contractor will work continuously until the asphalt base is completed.

Bid Items for this work are as follows: