



**COMMONWEALTH OF KENTUCKY
TRANSPORTATION CABINET**

Frankfort, Kentucky 40622
www.transportation.ky.gov/

Matthew G. Bevin
Governor

Greg Thomas
Secretary

October 17, 2019

CALL NO. 404
CONTRACT ID NO. 192293
ADDENDUM # 1

Subject: ALLEN COUNTY, 002GR19P068 - FD05
Letting October 25, 2019

(1) Added - Sidewalk Ramp and Detectable Warning Summary - Page 34(a) of 67

Proposal revisions are available at <http://transportation.ky.gov/Construction-Procurement/>.

If you have any questions, please contact us at 502-564-3500.

Sincerely,

A handwritten signature in black ink that reads "Rachel Mills".

Rachel Mills, P.E.
Director
Division of Construction Procurement

RM:mr
Enclosures



An Equal Opportunity Employer M/F/D

Allen County
SIDEWALK RAMP AND DETECTABLE WARNING SUMMARY
FD05 002 0100 014-018

INTERSECTION	RAMP		RAMP SY	DETECTABLE WARNING QUANTITY	DETECTABLE WARNING SF	DETECTABLE Retro Warning SF	NOTES
	TYPE						
14.901	S 1st street West	1	12.222		8		1.0 Side Street and 2.1 Main st Good 11.8 Side street 10 x 11
	N 1st street West					8	5.9 Main street 1.6 Side street Good 7.7 Side street Retro fit detectable
14.959	S 2nd street West	1	15.556		16		12.1 side street 20 x 5 and 8 x 5
	S 2nd street East	1 & 2	5.556		8		0.7 Side street Add new 10 x 5
	N 2nd street West	1	11.111		8		14.3 10 x 10
	N 2nd street East	3	5.556		8		1.6 Side street 5.7 side street Add new 10 X 5
15.013	S 3rd street West	1	7.222		8		5.8 Side street Good
	N 3rd street West	1	12		8		7.7 side street 12.1 Side street 13 x 5
	N 3rd street East	1	6		8		6.1 Side street 21 X 5
15.072	S 4th street West	1	4		8		7.9 Side street Retro Fit
	N 4th street West	1	8		16		10.7 Side street 13 X 4
	KY 98 North	1	7		8		1.1 Side street 5 X7 between Stop/remove Curb
	KY 98 South	1	59		8		8.0 Side street 5 x 5 10 x 5
15.141	East Maple NW	1	52		8		10.9 Side street 12 x 5
15.203	East Maple NE	1	60		8		Slope Adequate
15.203	East Maple SW	1	66		8		Use caution around curb wall
15.567	East Locust West	1	150		8		Slope Adequate Sidewalk is Landing
15.567	S 6th West	1	55		8		Retrofit in case rebuild can't be achieved
15.348	S 6th East	1	32		8		No existing connection to street
15.377	S 7th West	1	110		8		Sidewalk width not adequate
15.377	S 7th East	1	55		8		Sidewalk width not adequate
TOTAL			789	0	160	24	