Photo Inventory for Danville Connector

Project Item Number: 7-210

County and Route: Boyle, New Route

Project Description: Extend connector northeast of Danville from KY33 to KY34

Project Manager Contact information (Cabinet): Stuart Goodpaster, Joshua Samples, KYTC- D7, 859-246-2355

Project Manager Contact Information (Consultant): Wilbur Smith Associates, 859-254-5759

Other contacts: Phil Logsdon, KYTC-D7, 859-246-2355

Approximate dates: November 2000

Comments (number of people reached, effectiveness of the technique, what you would do differently, etc.): This exhibit was used at public meetings during the planning phase of the project. It helped people get oriented by identifying specific locations and issues in the project area and relating them to project mapping.

Appendix B

Images of the study area taken during the field visit of June 15, 2000.




Figure B-1. KY 2168, Danville Connector Map Showing the Locations of Images.



Image 1. South View of Tie-in of KY 2168 and KY 33.



Image 2. North View of Tie-in of KY 2168 and KY 33.



Image 3. Existing KY 2168 looking West.



Image 4. View East of KY 2168 and KY 33 Intersection.



Image 5. South View From KY 34.




Image 6. South View from KY 34.



Image 7. View Northwest KY 34.




Image 9. Warning Alarm at Intersection of KY 34 and KY 1804.



Image 8. South View of Corridor From KY 34.



Image 10. Intersection of KY 1805 and KY 34 Tie-in on Goggin Lane.




Image 11. View East from KY 1805 and KY 34.



Image 12. View Northeast of corridor crossing Waterworks Road.



Image 13. View Southwest of Corridor Tie-in to Existing KY 34.



Image 14. Historic Site on Waterworks Road at Right Angle Turn. Looking Due North.



Image 15. Historic Site on Waterworks Road Just After Right Angle Turn on Right Side.



Image 16. View North of Corridor Crossing KY 34. From KY 34, Two Historic Sites Right and Left of Center Tree on Ridge.



Image 17. Historic Site NW of Corridor at Crossing of KY 34.



Image 18. View Northwest of Corridor at Crossing of KY 34.



Image 19. Stone Fence along Waterworks Road.



Image 20. View North of Corridor Crossing KY 34 from KY 1805.



Image 21. View of Corridor Crossing south of KY 34. Archaeological Sites on Ridge Top.



Image 22. View of Corridor Crossing KY 34.



Image 23. View South of Corridor from Kemper Lane.



Image 24. View Northeast of Corridor Tie-in to Existing KY 34.



Image 25. View North from Kemper Lane at Corridor Crossing.



Image 26. View of Corridor North of Crossing with KY 1805.



Image 27. North View of Corridor Crossing KY 1805.



Image 28. South View of Corridor Crossing KY 1805.



Image 29. View South of Corridor Crossing Little Needmore Lane.



Image 30. View North of Corridor Crossing Little Needmore Lane.



Image 31. View South Corridor Crossing KY 52 at Pope Road.



Image 32. View Northwest of Corridor Crossing at Pope Road.



Image 33. View North of Corridor Crossing KY 52 and Pope Road.



Image 34. Transmission Line at Corridor Crossing on KY 1805.



Image 35. View of Relay Building at Intersection of KY 1805 and KY 52.



Image 36. View of Corridor Crossing on KY 52.

24



Image 37. View South of Corridor at Crossing of KY 52.



Image 38. View North of Corridor at Crossing of KY 52.



Image 39. View Northeast of Corridor as it Crosses US 150/KY 52 Before Tie-ing with Danville Bypass US 150.



Image 40. Tie-in of Corridor at US 150 Bypass and US 150/KY 52 Intersection.



Image 41. View Northeast of Historic Site at Corridor Tie-in with US 150.



Image 42. View Northwest of tie-in of Corridor with Danville Bypass US 150.



Image 43. Historic Site on Corridor off of Chrisman Lane.



Image 44. Historic Site on Corridor off of Chrisman Lane.



Image 45. Historic Site on Corridor off of Chrisman Lane.



Image 46. Historic Site on Corridor off of Chrisman Lane.



Image 47. Historic Site on Corridor off of Chrisman Lane.