



TRANSPORTATION CABINET

Frankfort, Kentucky 40622
www.transportation.ky.gov/

Steven L. Beshear
Governor

Michael W. Hancock, P.E.
Secretary

January 22, 2015

CALL NO. 403
CONTRACT ID NO. 152901
ADDENDUM # 1

Subject: Johnson-Lawrence County, 121GR15M005-FE02
Letting January 30, 2015

(1)Added - Drawing & Photos - Pages 17(a)-17(c) of 60

Proposal revisions are available at <http://transportation.ky.gov/Construction-Procurement/>.

If you have any questions, please contact us at 502-564-3500.

Sincerely,

A handwritten signature in blue ink that reads "Diana Castle Radcliffe".


Diana Castle Radcliffe
Director
Division of Construction Procurement

DR:ks
Enclosures



An Equal Opportunity Employer M/F/D

058B00041N
ORIGINAL BRIDGE DRAWING
FOR LOCATION PURPOSES ONLY



ELEVATION

5'-0" COMPOSITE T-BEAM SPAN, 87'-0" COMPOSITE I-BEAM SPAN
135'-225'-135" CONTINUOUS PLATE GIRDER SPANS
2'-0" 87'-0" COMPOSITE I-BEAM SPANS
TWO 2'-6" SAFETY CURBS - 36"-0" ROUNDOFF AT 10' SLOPES - 45° SKEW LEFT
REAR SHOULDER
44" SHOULDERS

LOCATION OF
LATERAL GUSSET
PLATE REPAIR

Note: All excavation that is within these limits & vertically upward excavation should be provided for as structure excavation.

PLAN OF ABUTMENT NO. 1
(Showing limits of Structure Excavation)

PLAN LAYOUT

SECTION A-A

C10 Minor Bridge Denomination FH 630
BRIDGE OVER LEVISA FORK
SHEET 2
COMMONWEALTH OF KENTUCKY
DEPARTMENT OF HIGHWAYS
COUNTY OF
JOHNSON
PAINTSVILLE-AUXIER-PRESTONSBURG
BRIDGE NUMBER 2833 + 10-337 PROJECT NO. 1484

Track Answer Section in Bourse
This will be provided by Department of
Highways. Contractor Cost of work shown is included
and it will meet by the designer's answer



DATE	BY	CHKD
7/1/12		

058B00041N
LATERAL GUSSET PLATE
REPAIR



058B00041N
LATERAL GUSSET PLATE
REPAIR

