

Route:	County	Pvmnt Type	Last Rehab Year	From:	To:	Length:	Adt	Adt Year	Test Date	Direction	IRI Lane 1	IRI Lane 2
KY9000	CLARK	AC/PCC	2000	0.000	3.648	3.648	11450	2013	8/16/2012	EB	53.7	
KY9000	CLARK	AC/PCC	2000	0.000	3.648	3.648	11450	2013	8/16/2012	WB	67.6	
KY9000	CLARK	AC/PCC	2000	3.648	11.913	8.265	11450	2013	12/17/2011	EB	47.7	
KY9000	CLARK	AC/PCC	2000	3.648	5.311	1.663	11450	2013	12/17/2011	WB	57.7	
KY9000	CLARK	AC/PCC	2008	5.311	11.913	6.602	11450	2013	12/17/2011	WB	51.6	
KY9000	POWELL	AC/PCC	2007	11.913	16.020	4.107	11450	2013	12/17/2011	EB	33.6	
KY9000	POWELL	AC/PCC	2007	11.913	16.020	4.107	11450	2013	12/17/2011	WB	41.6	
KY9000	POWELL	AC/PCC	2007	16.020	19.150	3.130	11431	2013	12/17/2011	EB	36.7	
KY9000	POWELL	AC/PCC	2007	16.020	19.150	3.130	11431	2013	12/17/2011	WB	33.4	
KY9000	POWELL	AC/PCC	2011	19.150	22.307	3.157	11934	2013	12/17/2011	EB	49.8	
KY9000	POWELL	AC/PCC	2011	19.150	22.307	3.157	11934	2013	12/17/2011	WB	45.7	
KY9000	POWELL	AC/PCC	1999	22.307	27.376	5.069	9011	2013	12/17/2011	EB	86.2	
KY9000	POWELL	AC/PCC	1999	22.307	27.376	5.069	9011	2013	12/17/2011	WB	72.2	
KY9000	POWELL	AC/PCC	2000	27.376	32.788	5.412	9011	2013	12/17/2011	EB	56.1	
KY9000	POWELL	AC/PCC	2000	27.376	32.788	5.412	9011	2013	12/17/2011	WB	61.7	
KY9000	POWELL	AC/PCC	2011	32.788	35.280	2.492	7292	2013	12/17/2011	EB	49.5	
KY9000	POWELL	AC/PCC	2011	32.788	35.280	2.492	7292	2013	12/17/2011	WB	67.8	
KY9000	POWELL	AC/PCC	1990	35.280	36.000	0.720	7283	2013	12/17/2011	EB	86.4	
KY9000	POWELL	AC/PCC	1990	35.280	36.000	0.720	7283	2013	12/17/2011	WB	53.6	
KY9000	WOLFE	AC/PCC	2006	36.000	39.513	3.513	7283	2013	12/17/2011	EB	56.5	
KY9000	WOLFE	AC/PCC	2006	36.000	39.513	3.513	7283	2013	12/17/2011	WB	63.7	
KY9000	WOLFE	AC/PCC	2006	39.513	43.104	3.591	9199	2013	7/24/2012	EB	78.2	
KY9000	WOLFE	AC/PCC	2006	39.513	43.104	3.591	9199	2013	7/24/2012	WB	58.1	68.8
WK9001	HOPKINS	AC/PCC	1997	38.326	38.966	0.640	13273	2013	3/1/2012	EB	86.1	
WK9001	HOPKINS	AC/PCC		38.326	40.258	1.932	13273	2013	3/1/2012	WB	74.7	
WK9001	HOPKINS	AC/PCC	1997	38.966	42.807	3.841	13273	2013	3/1/2012	EB	75.0	
WK9001	HOPKINS	AC/PCC	1996	40.258	42.807	2.549	13273	2013	3/1/2012	WB	66.4	
WK9001	HOPKINS	AC/PCC	2007	42.807	45.950	3.143	13273	2013	3/1/2012	EB	50.4	
WK9001	HOPKINS	AC/PCC	2007	42.807	45.950	3.143	13273	2013	3/1/2012	WB	43.3	
WK9001	MUHLENBERG	AC/PCC	1999	45.950	52.535	6.585	11918	2013	3/1/2012	EB	79.2	
WK9001	MUHLENBERG	AC/PCC	1997	45.950	49.900	3.950	12344	2013	3/1/2012	WB	72.4	
WK9001	MUHLENBERG	AC/PCC	1999	49.900	52.535	2.635	11280	2013	3/1/2012	WB	92.3	
WK9001	MUHLENBERG	AC/PCC	2011	52.535	54.285	1.750	9488	2013	3/1/2012	EB	47.9	
WK9001	MUHLENBERG	AC/PCC	2011	52.535	54.285	1.750	9488	2013	3/1/2012	WB	44.9	
WK9001	MUHLENBERG	AC/PCC	2000	54.285	59.920	5.635	9338	2013	3/1/2012	EB	90.9	
WK9001	MUHLENBERG	AC/PCC	2000	54.285	59.920	5.635	9338	2013	3/1/2012	WB	82.5	
WK9001	MUHLENBERG	AC/PCC	2007	59.920	65.375	5.455	9062	2013	3/1/2012	EB	59.9	
WK9001	MUHLENBERG	AC/PCC	2007	59.920	62.870	2.950	9062	2013	3/1/2012	WB	55.5	
WK9001	MUHLENBERG	AC/PCC	2007	62.870	65.375	2.505	9062	2013	3/1/2012	WB	49.4	
WK9001	OHIO	AC/PCC	2003	65.720	83.350	17.630	8853	2013	3/1/2012	EB	54.5	
WK9001	OHIO	AC/PCC	2003	65.720	83.350	17.630	8853	2013	3/1/2012	WB	49.6	
WK9001	OHIO	AC/PCC	2006	83.350	91.100	7.750	7622	2013	6/26/2012	EB	50.7	
WK9001	OHIO	AC/PCC	2006	83.350	91.100	7.750	7622	2013	6/26/2012	WB	58.1	
WK9001	GRAYSON	AC/PCC	1991	91.100	95.030	3.930	7794	2013	6/26/2012	EB	98.5	
WK9001	GRAYSON	AC/PCC	1999	91.100	95.030	3.930	7794	2013	6/26/2012	WB	47.9	
WK9001	GRAYSON	AC/PCC	2008	95.030	100.250	5.220	8464	2013	6/26/2012	EB	72.7	
WK9001	GRAYSON	AC/PCC	2008	95.030	100.250	5.220	8464	2013	6/26/2012	WB	72.1	
WK9001	GRAYSON	AC/PCC	1998	100.250	103.976	3.726	8464	2013	6/26/2012	EB	56.6	
WK9001	GRAYSON	AC/PCC	2003	100.250	103.976	3.726	8464	2013	6/26/2012	WB	95.5	
WK9001	GRAYSON	AC/PCC	1998	103.976	106.080	2.104	8464	2013	6/26/2012	EB	60.2	
WK9001	GRAYSON	AC/PCC	1998	103.976	106.080	2.104	8464	2013	6/26/2012	WB	67.2	

Route:	County	Pvmnt Type	Last Rehab Year	From:	To:	Length:	Adt	Adt Year	Test Date	Direction	IRI Lane 1	IRI Lane 2
WK9001	GRAYSON	AC/PCC	1993	106.080	107.750	1.670	9205	2013	6/26/2012	EB	110.7	
WK9001	GRAYSON	AC/PCC	2003	106.080	109.050	2.970	9571	2013	6/26/2012	WB	76.5	
WK9001	GRAYSON	AC/PCC	2005	107.750	111.250	3.500	10041	2013	6/26/2012	EB	65.8	
WK9001	GRAYSON	AC/PCC	2002	109.050	110.500	1.450	10041	2013	6/26/2012	WB	54.4	
WK9001	GRAYSON	AC/PCC	2007	110.500	112.550	2.050	10494	2013	6/26/2012	WB	64.6	
WK9001	GRAYSON	AC/PCC	2007	111.250	112.550	1.300	10756	2013	6/26/2012	EB	81.4	
WK9001	GRAYSON	AC/PCC	2003	112.550	114.800	2.250	11419	2013	6/26/2012	EB	55.1	
WK9001	GRAYSON	AC/PCC	2003	112.550	114.800	2.250	11419	2013	6/26/2012	WB	68.0	
WK9001	GRAYSON	AC/PCC	2009	114.800	116.950	2.150	11419	2013	6/26/2012	EB	58.9	
WK9001	GRAYSON	AC/PCC	1993	114.800	116.950	2.150	11419	2013	6/26/2012	WB	101.2	
WK9001	GRAYSON	AC	2002	116.950	119.649	2.699	11419	2013	6/26/2012	EB	72.4	
WK9001	GRAYSON	AC	2002	116.950	119.649	2.699	11419	2013	6/26/2012	WB	68.8	
WK9001	GRAYSON	AC	2011	119.649	120.649	1.000	11419	2013	3/1/2012	EB	30.6	
WK9001	GRAYSON	AC	2011	119.649	120.649	1.000	11419	2013	3/1/2012	WB	32.8	
WK9001	HARDIN	AC	2005	120.649	123.474	2.825	11419	2013	3/1/2012	WB	51.7	
WK9001	HARDIN	AC	2005	120.930	123.474	2.544	11419	2013	3/1/2012	EB	61.8	
WK9001	HARDIN	AC	2005	123.474	132.620	9.146	11848	2013	3/1/2012	EB	56.9	
WK9001	HARDIN	AC	2005	123.474	130.948	7.474	11848	2013	3/1/2012	WB	52.2	
WK9001	HARDIN	AC	2002	130.948	135.100	4.152	11848	2013	3/1/2012	WB	69.9	
WK9001	HARDIN	AC	2002	132.620	134.923	2.303	11848	2013	3/1/2012	EB	53.6	
WK9001	HARDIN	A	2011	134.923	135.923	1.000	13189	2013	3/1/2012	EB	41.0	
WK9001	HARDIN	AC	2011	135.100	136.066	0.966	15091	2013	3/1/2012	WB	44.2	
WK9001	HARDIN	AC	2002	135.923	136.796	0.873	22931	2013	3/1/2012	EB	69.7	
WK9001	HARDIN	AC	2002	136.066	136.796	0.730	22647	2013	3/1/2012	WB	78.9	
BG9002	HARDIN	AC	2007	0.000	4.900	4.900	12453	2013	4/10/2011	EB	58.0	
BG9002	HARDIN	AC	2007	0.000	4.900	4.900	12453	2013	3/1/2012	WB	50.3	
BG9002	HARDIN	AC	2006	4.900	5.820	0.920	12453	2013	4/10/2011	EB	63.2	
BG9002	HARDIN	AC	2006	4.900	5.820	0.920	12453	2013	3/1/2012	WB	54.4	
BG9002	HARDIN	AC	2003	5.820	10.172	4.352	12147	2013	3/1/2012	EB	47.3	
BG9002	HARDIN	AC	2003	5.820	10.172	4.352	12147	2013	3/1/2012	WB	47.0	
BG9002	NELSON	AC	2007	10.172	16.540	6.368	12523	2013	3/1/2012	EB	49.8	
BG9002	NELSON	AC	2007	10.172	17.558	7.386	12523	2013	3/1/2012	WB	47.4	
BG9002	NELSON	AC	2007	16.540	24.240	7.700	12517	2013	3/1/2012	EB	48.3	
BG9002	NELSON	AC	1995	17.558	24.240	6.682	12516	2013	3/1/2012	WB	104.7	
BG9002	NELSON	PCC	1991	24.240	29.180	4.940	11586	2013	3/1/2012	EB	140.8	
BG9002	NELSON	PCC	1991	24.240	29.180	4.940	11586	2013	3/1/2012	WB	118.0	
BG9002	NELSON	AC	1991	29.180	35.150	5.970	11033	2013	3/1/2012	EB	34.8	
BG9002	NELSON	AC/PCC	1991	29.180	35.150	5.970	11033	2013	3/1/2012	WB	31.9	
BG9002	NELSON	AC/PCC	2000	35.150	39.267	4.117	9901	2013	3/1/2012	EB	51.8	
BG9002	NELSON	AC/PCC	2000	35.150	39.267	4.117	9901	2013	3/1/2012	WB	49.0	
BG9002	WASHINGTON	AC/PCC	2001	39.267	41.790	2.523	10115	2013	3/1/2012	EB	102.4	
BG9002	WASHINGTON	AC/PCC	2001	39.267	41.790	2.523	10115	2013	3/1/2012	WB	88.1	
BG9002	WASHINGTON	AC/PCC	2001	41.790	44.807	3.017	11291	2013	3/1/2012	EB	128.1	
BG9002	WASHINGTON	AC/PCC	2001	41.790	44.807	3.017	11291	2013	3/1/2012	WB	102.0	
BG9002	ANDERSON	AC/PCC	1996	44.807	47.690	2.883	11291	2013	3/1/2012	EB	116.5	
BG9002	ANDERSON	AC/PCC	1996	44.807	47.690	2.883	11291	2013	3/1/2012	WB	91.4	
BG9002	ANDERSON	AC/PCC	1996	47.690	51.838	4.148	7778	2013	3/1/2012	EB	86.6	
BG9002	ANDERSON	AC/PCC	1996	47.690	51.838	4.148	7778	2013	3/1/2012	WB	92.2	
BG9002	MERCER	AC/PCC	2002	51.838	56.287	4.449	7649	2013	3/1/2012	EB	45.3	
BG9002	MERCER	AC/PCC	1995	51.838	56.287	4.449	7649	2013	3/1/2012	WB	90.2	
BG9002	ANDERSON	AC/PCC	1999	56.287	59.590	3.303	10021	2013	3/1/2012	EB	71.6	

Route:	County	Pvmnt Type	Last Rehab Year	From:	To:	Length:	Adt	Adt Year	Test Date	Direction	IRI Lane 1	IRI Lane 2
BG9002	ANDERSON	AC/PCC	2011	56.287	59.590	3.303	10021	2013	3/1/2012	WB	70.3	
BG9002	ANDERSON	AC	1996	59.590	61.841	2.251	17493	2013	3/1/2012	EB	92.3	
BG9002	ANDERSON	AC	2011	59.590	61.841	2.251	17493	2013	3/1/2012	WB	40.0	
BG9002	WOODFORD	AC	2008	62.047	71.134	9.087	18383	2013	3/1/2012	EB	51.5	
BG9002	WOODFORD	AC	2007	62.047	71.134	9.087	18383	2013	3/1/2012	WB	45.5	
JC9003	FULTON	AC	2012	0.000	1.781	1.781	7799	2013	8/31/2012	NB	85.4	
JC9003	FULTON	AC	2012	0.000	1.781	1.781	7799	2013	8/31/2012	SB	75.7	
JC9003	FULTON	AC	2008	1.781	9.077	7.296	7607	2013	8/31/2012	NB	53.0	
JC9003	FULTON	AC	2008	1.781	9.077	7.296	7607	2013	8/31/2012	SB	51.1	
JC9003	GRAVES	AC	2006	9.077	13.645	4.568	7669	2013	8/31/2012	NB	46.4	
JC9003	GRAVES	AC	2006	9.077	13.645	4.568	7669	2013	8/31/2012	SB	53.0	
JC9003	GRAVES	AC	2005	13.645	21.887	8.242	9144	2013	8/31/2012	NB	58.6	
JC9003	GRAVES	AC	2005	13.645	21.000	7.355	8711	2013	8/31/2012	SB	54.7	
JC9003	GRAVES	AC	2007	21.000	25.384	4.384	12743	2013	8/31/2012	SB	65.7	
JC9003	GRAVES	AC	2007	21.887	25.384	3.497	12746	2013	8/31/2012	NB	58.6	
JC9003	GRAVES	AC	2007	25.384	39.920	14.536	6579	2013	8/31/2012	NB	40.9	
JC9003	GRAVES	AC	2007	25.384	39.920	14.536	6579	2013	8/31/2012	SB	46.5	
JC9003	MARSHALL	AC	2008	39.920	52.333	12.413	14561	2013	8/31/2012	NB	57.5	
JC9003	MARSHALL	AC	2008	39.920	52.333	12.413	14561	2013	8/31/2012	SB	48.2	
EB9004	CHRISTIAN	AC/PCC	1995	6.770	10.700	3.930	12351	2013	12/31/2012	NB	69.7	
EB9004	CHRISTIAN	AC/PCC	1999	6.770	10.700	3.930	12351	2013	12/31/2012	SB	69.3	
EB9004	CHRISTIAN	AC/PCC	1994	10.700	12.130	1.430	11357	2013	12/31/2012	NB	79.9	
EB9004	CHRISTIAN	AC/PCC	1995	10.700	16.500	5.800	10693	2013	12/31/2012	SB	62.2	
EB9004	CHRISTIAN	AC/PCC	2005	12.130	16.500	4.370	10476	2013	12/31/2012	NB	52.0	
EB9004	CHRISTIAN	PCC	2008	16.500	22.480	5.980	10476	2013	12/31/2012	NB	84.9	
EB9004	CHRISTIAN	PCC	2008	16.500	22.480	5.980	10476	2013	12/31/2012	SB	83.2	
EB9004	CHRISTIAN	PCC	2008	22.480	29.910	7.430	9974	2013	12/31/2012	NB	69.5	
EB9004	CHRISTIAN	PCC	2008	22.480	29.910	7.430	9974	2013	12/31/2012	SB	78.9	
EB9004	HOPKINS	AC/PCC	2006	29.910	33.200	3.290	12759	2013	12/25/2011	NB	56.9	
EB9004	HOPKINS	AC/PCC	1990	29.910	31.360	1.450	12607	2013	8/11/2010	SB	94.5	
EB9004	HOPKINS	AC/PCC	1990	31.360	32.861	1.501	12607	2013	8/11/2010	SB	111.3	
EB9004	HOPKINS	AC/PCC	1990	32.861	35.550	2.689	17457	2013	6/27/2012	SB	116.8	
EB9004	HOPKINS	AC/PCC	2001	33.200	39.794	6.594	20413	2013	6/27/2012	NB	68.6	
EB9004	HOPKINS	AC/PCC	2007	35.550	37.070	1.520	21175	2013	6/27/2012	SB	71.3	
EB9004	HOPKINS	AC/PCC	1998	37.070	42.418	5.348	22118	2013	6/27/2012	SB	95.7	
EB9004	HOPKINS	AC/PCC	1996	39.794	42.446	2.652	22165	2013	6/27/2012	NB	78.9	
EB9004	HOPKINS	AC/PCC	2011	42.418	46.100	3.682	23277	2013	6/27/2012	SB	67.2	
EB9004	HOPKINS	AC/PCC	2011	42.446	46.100	3.654	23252	2013	6/27/2012	NB	50.9	
EB9004	HOPKINS	AC/PCC	2005	46.100	53.110	7.010	15576	2013	6/27/2012	NB	52.5	
EB9004	HOPKINS	AC/PCC	2005	46.100	53.110	7.010	15576	2013	6/27/2012	SB	63.9	
EB9004	WEBSTER	AC/PCC	2008	53.110	61.850	8.740	13761	2013	6/27/2012	NB	95.6	
EB9004	WEBSTER	AC/PCC	2008	53.110	61.850	8.740	13761	2013	6/27/2012	SB	100.2	
EB9004	WEBSTER	AC/PCC	2008	61.850	65.393	3.543	12601	2013	6/27/2012	NB	54.4	
EB9004	WEBSTER	AC/PCC	2008	61.850	65.393	3.543	12601	2013	6/27/2012	SB	72.4	
EB9004	HENDERSON	AC/PCC	2008	65.393	70.450	5.057	11907	2013	6/27/2012	NB	85.5	
EB9004	HENDERSON	AC/PCC	2008	65.393	70.450	5.057	11907	2013	6/27/2012	SB	80.6	
EB9004	HENDERSON	AC/PCC	2006	70.450	78.248	7.798	13703	2013	6/27/2012	NB	57.5	
EB9004	HENDERSON	AC/PCC	2006	70.450	78.306	7.856	13768	2013	8/28/2012	SB	70.1	
AU9005	HENDERSON	PCC	2010	0.000	8.750	8.750	9811	2013	8/28/2012	EB	163.7	
AU9005	HENDERSON	PCC	2010	0.000	8.750	8.750	9811	2013	8/28/2012	WB	156.7	
AU9005	HENDERSON	PCC	2011	8.750	15.883	7.133	9880	2013	8/28/2012	EB	74.3	

Route:	County	Pvmnt Type	Last Rehab Year	From:	To:	Length:	Adt	Adt Year	Test Date	Direction	IRI Lane 1	IRI Lane 2
AU9005	HENDERSON	PCC	2011	8.750	15.883	7.133	9880	2013	8/28/2012	WB	60.8	
AU9005	DAVISS	PCC	2010	15.883	23.441	7.558	10591	2013	8/28/2012	EB	146.8	
AU9005	DAVISS	PCC	2010	15.883	23.441	7.558	10591	2013	8/28/2012	WB	138.1	
HR9006	LAUREL	AC/PCC	2001	0.000	0.845	0.845	14047	2013	11/14/2012	EB	90.8	
HR9006	LAUREL	AC/PCC	2001	0.000	0.845	0.845	14047	2013	11/14/2012	WB	66.9	
HR9006	LAUREL	AC/PCC	2001	0.845	3.877	3.032	10662	2013	11/14/2012	EB	55.0	
HR9006	LAUREL	AC/PCC	2001	0.845	3.877	3.032	10662	2013	11/14/2012	WB	58.8	
HR9006	LAUREL	AC/PCC	2002	3.877	8.800	4.923	7972	2013	11/14/2012	EB	53.4	
HR9006	LAUREL	AC/PCC	2002	3.877	8.800	4.923	7972	2013	11/14/2012	WB	47.4	
HR9006	CLAY	AC	1993	8.800	14.345	5.545	7972	2013	11/14/2012	EB	86.7	
HR9006	CLAY	AC	1993	8.800	15.000	6.200	7972	2013	11/14/2012	WB	88.2	
HR9006	CLAY	AC	2011	14.345	19.500	5.155	7972	2013	11/14/2012	EB	57.9	
HR9006	CLAY	AC	2011	15.000	19.500	4.500	7972	2013	11/14/2012	WB	49.8	
HR9006	CLAY	AC/PCC	2003	19.500	28.400	8.900	7972	2013	11/14/2012	EB	46.0	
HR9006	CLAY	AC/PCC	2003	19.500	28.400	8.900	7972	2013	11/14/2012	WB	47.4	
HR9006	CLAY	AC/PCC	1999	28.400	31.000	2.600	6385	2013	11/14/2012	EB	40.0	
HR9006	CLAY	AC/PCC	1999	28.400	31.000	2.600	6385	2013	11/14/2012	WB	44.8	
HR9006	CLAY	AC/PCC	2004	31.000	35.080	4.080	5291	2013	11/14/2012	EB	43.8	
HR9006	CLAY	AC/PCC	2004	31.000	35.080	4.080	5291	2013	11/14/2012	WB	43.4	
HR9006	LESLIE	AC	2007	35.080	39.000	3.920	5322	2013	11/14/2012	EB	52.8	
HR9006	LESLIE	AC	2007	35.080	39.000	3.920	5322	2013	11/14/2012	WB	57.1	
HR9006	LESLIE	AC	2005	39.000	43.926	4.926	5322	2013	11/14/2012	EB	48.8	
HR9006	LESLIE	AC	2005	39.000	43.926	4.926	5322	2013	11/14/2012	WB	47.6	
HR9006	LESLIE	AC/PCC	2005	43.926	44.350	0.424	5746	2013	11/14/2012	EB	52.8	
HR9006	LESLIE	AC/PCC	2005	43.926	44.350	0.424	5746	2013	11/14/2012	WB	42.4	
HR9006	LESLIE	AC	2005	44.350	51.026	6.676	6433	2013	11/14/2012	EB	45.6	
HR9006	LESLIE	AC	2005	44.350	51.026	6.676	6433	2013	11/14/2012	WB	45.7	
HR9006	PERRY	AC	2000	51.026	53.062	2.036	6433	2013	11/14/2012	EB	63.2	
HR9006	PERRY	AC	2000	51.026	53.062	2.036	6433	2013	11/14/2012	WB	66.7	
HR9006	PERRY	AC	2007	53.062	55.966	2.904	6433	2013	11/14/2012	EB	67.9	
HR9006	PERRY	AC	2007	53.062	55.966	2.904	6433	2013	11/14/2012	WB	66.5	
HR9006	PERRY	AC	2000	55.966	57.166	1.200	9257	2013	11/14/2012	EB	69.2	
HR9006	PERRY	AC	2000	55.966	57.166	1.200	9257	2013	11/14/2012	WB	79.7	
HR9006	PERRY	AC	1994	57.166	59.088	1.922	13166	2013	11/14/2012	EB	81.3	
HR9006	PERRY	AC	1994	57.166	59.088	1.922	13166	2013	11/14/2012	WB	97.9	
WN9007	WARREN	AC	2011	0.000	2.600	2.600	4082	2013	7/9/2012	NB	38.3	
WN9007	WARREN	AC	2011	0.000	2.600	2.600	4082	2013	5/11/2012	SB	64.2	
WN9007	WARREN	AC	1991	2.600	9.200	6.600	17247	2013	7/9/2012	NB	65.6	
WN9007	WARREN	AC	1991	2.600	7.100	4.500	19732	2013	5/11/2012	SB	86.8	
WN9007	WARREN	AC	1991	7.100	9.200	2.100	11922	2013	5/11/2012	SB	105.2	
WN9007	WARREN	AC	2007	9.200	17.800	8.600	10264	2013	7/9/2012	NB	42.1	
WN9007	WARREN	AC	2007	9.200	17.800	8.600	10264	2013	5/11/2012	SB	54.2	
WN9007	BUTLER	AC	2007	17.800	28.500	10.700	10204	2013	7/9/2012	NB	43.3	
WN9007	BUTLER	AC	2007	17.800	28.500	10.700	10204	2013	5/11/2012	SB	58.5	
WN9007	BUTLER	AC	2011	28.500	34.724	6.224	8611	2013	7/9/2012	NB	39.2	
WN9007	BUTLER	AC	2011	28.500	34.724	6.224	8611	2013	5/11/2012	SB	60.2	
WN9007	BUTLER	PCC	2012	34.724	37.143	2.419	8123	2013	7/9/2012	NB	96.0	
WN9007	BUTLER	PCC	2012	34.724	37.143	2.419	8123	2013	5/11/2012	SB	88.5	
WN9007	OHIO	PCC	2009	37.143	44.350	7.207	8083	2013	7/9/2012	NB	75.3	
WN9007	OHIO	PCC	2009	37.143	44.350	7.207	8083	2013	5/11/2012	SB	106.5	
WN9007	OHIO	PCC	2009	44.350	49.795	5.445	8898	2013	5/7/2012	NB	78.7	

Route:	County	Pvmnt Type	Last Rehab Year	From:	To:	Length:	Adt	Adt Year	Test Date	Direction	IRI Lane 1	IRI Lane 2
WN9007	OHIO	PCC	2009	44.350	49.795	5.445	8898	2013	5/8/2012	SB	115.7	
WN9007	OHIO	AC/PCC	2006	49.795	59.080	9.285	9819	2013	5/7/2012	NB	56.5	
WN9007	OHIO	AC/PCC	2006	49.795	59.080	9.285	9819	2013	5/8/2012	SB	87.5	
WN9007	OHIO	AC/PCC	2007	59.080	65.910	6.830	9829	2013	5/8/2012	SB	81.9	
WN9007	OHIO	AC/PCC	2007	59.880	65.910	6.030	9829	2013	5/7/2012	NB	52.9	
WN9007	DAVIESS	AC/PCC	2004	65.910	70.910	5.000	9829	2013	5/7/2012	NB	48.1	
WN9007	DAVIESS	AC/PCC	2006	65.910	72.264	6.354	9829	2013	5/8/2012	SB	72.0	
WN9007	DAVIESS	AC/PCC	2003	70.910	72.264	1.354	9829	2013	5/7/2012	NB	61.8	
LN9008	BARREN	AC	1993	0.000	9.000	9.000	9399	2013	9/19/2012	EB	54.0	
LN9008	BARREN	AC	1993	0.000	9.000	9.000	9399	2013	12/31/2012	WB	59.2	
LN9008	BARREN	AC	2007	9.000	14.850	5.850	9057	2013	9/19/2012	EB	42.2	
LN9008	BARREN	AC	2007	9.000	16.000	7.000	8648	2013	9/19/2012	WB	45.7	
LN9008	BARREN	AC	2007	14.850	16.117	1.267	6569	2013	9/19/2012	EB	56.4	
LN9008	BARREN	AC	2007	16.000	20.100	4.100	6569	2013	9/19/2012	WB	46.7	
LN9008	BARREN	AC	2007	16.117	20.100	3.983	6569	2013	9/19/2012	EB	43.3	
LN9008	METCALFE	AC	2005	20.100	28.052	7.952	6398	2013	9/19/2012	EB	48.8	
LN9008	METCALFE	AC	2005	20.100	28.052	7.952	6398	2013	9/19/2012	WB	45.2	
LN9008	METCALFE	AC	2005	28.052	36.159	8.107	4495	2013	9/19/2012	EB	55.5	
LN9008	METCALFE	AC	2005	28.052	36.159	8.107	4495	2013	9/19/2012	WB	55.4	
LN9008	ADAIR	AC	1999	36.159	43.020	6.861	4495	2013	9/19/2012	EB	69.3	
LN9008	ADAIR	AC	1999	36.159	43.020	6.861	4495	2013	9/19/2012	WB	67.2	
LN9008	ADAIR	AC	2007	43.020	48.083	5.063	5084	2013	9/19/2012	EB	41.5	
LN9008	ADAIR	AC	2007	43.020	48.083	5.063	5084	2013	12/31/2012	WB	46.6	
LN9008	ADAIR	AC	2007	48.083	53.892	5.809	6316	2013	9/19/2012	EB	34.6	
LN9008	ADAIR	AC	2007	48.083	53.892	5.809	6316	2013	12/31/2012	WB	39.8	
LN9008	ADAIR	AC	2007	53.892	62.500	8.608	6282	2013	9/19/2012	EB	36.2	
LN9008	ADAIR	AC	2007	53.892	62.500	8.608	6282	2013	12/31/2012	WB	40.5	
LN9008	RUSSELL	AC	2008	62.500	72.100	9.600	6464	2013	9/19/2012	EB	35.6	
LN9008	RUSSELL	AC	2008	62.500	72.100	9.600	6464	2013	12/31/2012	WB	43.5	
LN9008	PULASKI	AC	1992	72.100	76.550	4.450	6464	2013	9/19/2012	EB	76.2	
LN9008	PULASKI	AC	1996	72.100	76.550	4.450	6464	2013	12/31/2012	WB	69.1	
LN9008	PULASKI	AC	1991	76.550	84.309	7.759	7010	2013	9/19/2012	EB	74.5	
LN9008	PULASKI	AC	1992	76.550	84.309	7.759	7010	2013	12/31/2012	WB	83.5	
LN9008	PULASKI	AC	1991	84.640	88.241	3.601	7176	2013	9/19/2012	EB	44.1	
LN9008	PULASKI	AC	1991	84.640	88.241	3.601	7176	2013	12/31/2012	WB	53.8	
KY9009	WOLFE	AC	2003	43.104	55.434	12.330	4238	2013	11/16/2012	WB	54.6	57.9
KY9009	WOLFE	AC	2003	46.400	55.434	9.034	4332	2013	12/17/2011	EB	62.2	
KY9009	WOLFE	AC	2002	55.434	59.500	4.066	4761	2013	12/17/2011	EB	74.9	
KY9009	WOLFE	AC	2002	55.434	59.500	4.066	4761	2013	11/16/2012	WB	61.4	
KY9009	MORGAN	AC	2002	59.500	63.084	3.584	4685	2013	12/17/2011	EB	63.4	
KY9009	MORGAN	AC	2002	59.500	63.084	3.584	4685	2013	11/16/2012	WB	61.6	
KY9009	MAGOFFIN	AC	2002	63.084	67.400	4.316	4685	2013	12/17/2011	EB	69.1	
KY9009	MAGOFFIN	AC	2002	63.084	67.400	4.316	4685	2013	11/16/2012	WB	62.2	
KY9009	MAGOFFIN	AC	2002	67.400	71.650	4.250	4685	2013	12/17/2011	EB	75.0	
KY9009	MAGOFFIN	AC	2002	67.400	71.650	4.250	4685	2013	11/16/2012	WB	65.6	
KY9009	MAGOFFIN	AC	2002	71.650	74.506	2.856	5764	2013	12/17/2011	EB	93.9	
KY9009	MAGOFFIN	AC	2002	71.650	74.506	2.856	5764	2013	11/16/2012	WB	72.2	
KY9009	MAGOFFIN	AC	1995	74.506	75.318	0.812	7324	2013	12/17/2011	EB	115.5	
KY9009	MAGOFFIN	AC	1995	74.506	75.318	0.812	7324	2013	11/16/2012	WB	70.2	
KY9009	MAGOFFIN	AC	1993	75.318	75.627	0.309	8188	2013	12/17/2011	EB	135.5	
KY9009	MAGOFFIN	AC	1993	75.318	75.627	0.309	8188	2013	11/16/2012	WB	64.6	