

[Back to Home](#)

3-11-10

[2010-09 Statewide Airport Pavement Management](#)

**QUESTION:** Will the Kentucky Transportation Cabinet provide the consultant with historical pavement data for each airport or will it be the responsibility of the consultant to obtain historical data from each airport or their consultants?

**RESPONSE:** The KY Department of Aviation does not have consistent or reliable historical pavement data for each airport. It will be the responsibility of the consultant to collect any pertinent information from the respective sources, most likely the Airport Board or Airport Board's engineering consultant.

3-16-10

[2010-09 Wolfe County 10-1086 KY191](#)

**QUESTION:** The bulletin and the active six-year plan website say the sufficiency rating for B00002N is 21.2, however, the 3/5/09 bridge inspection report says 43.4 with the next inspection due 3/5/11.

**RESPONSE:** The Sufficiency rating shown as 21.1 is incorrect. The sufficiency rating for B00002N is 43.4 is correct .

**CORRECTION:** Photogrammetric Services: “Photogrammetry is not required, Conventional Survey Methods by the consultant will be applied to this project”.

**CORRECTION:** Project Funding: Federal Funds (BRX)

**The above Q & A section is dealing with the 2010-09 Project Listing (Former name Bulletins)**