

Calibration

**W. Pierre Peltier
Technical Sales**

And

**Business Development
Terry Asphalt Materials
Inc.**



What will we cover?

- Basics of calibration



History of Calibration Process

- In early days of industry, calibration performed by operator judgment.
- Worked fine for unmodified, slow set slurry.
- Introduction of polymer modified emulsions required conforming to tighter specifications.
- Results in better quality control of the product.



What is calibration?

- **Process of measuring by weight**
 - **Actual output of:**
 - **Aggregate**
 - **Emulsion**
 - **Fines (dependent on machine make)**
- **Correlated to revolutions of the aggregate belt**
- **Recorded by a counter**



Why do we calibrate?

- **Allow the machine to be set such that the ratios of aggregate, emulsion and fines stay fixed at a predetermined level.**
- **Ensure quality control of the system for the contractor and buying agency**




How do we calibrate?


- **The mix design specifies the amount of emulsion as a percentage of the amount of aggregate, by weight.**
- **For example, a 10% mix design means the weight of the emulsion shall be 10% of the weight of the aggregate. To then switch to a 12% mix design requires changing the quantity of emulsion or aggregate.**
- **If we mixed in a batch...**

How do we calibrate?

10%




Emulsion – 10 lbs




Rock – 100 lbs

12%




Emulsion – 12 lbs



Rock – 100 lbs

Machine Calibration



Since we have a continuous feed operation, we must match the aggregate delivery to the emulsion pump delivery.

This is done with “counters” which are also known as totalizers.



Counters


- **Count, or totalize the revolutions of a shaft, pulley or sprocket.**
- **In some applications, counts fractions of a revolution.**
- **Counters are not rate dependent.**

Counter example

Counter Example



0





0




0







0







0







0







0





0






0



1




1






1






1






1





1






1







1






2




2



2





2





2





2



2




2



3




3






3







3





3





3



3






3



4




4






4






4






4






4






4






4



5




5






5






5






5





5






5






5



6




6






6






6






6





6





6





6



7




7






7






7






7





7





7






7





8






8







8






8






8






8






8






8






9




9



9





9





9





9



9





9




10






10






10






10






10





10





10






10




Machine Operation

The aggregate is delivered by a conveyor belt, delivering a consistent amount of aggregate (at a given gate setting) from the hopper into the pugmill.



Machine Operation



Machine Operation


Emulsion is delivered by a pump.

- **Positive Displacement**
 - **Gear Pump**




Gear Pump with strainer

Gear Pump (Positive Displacement)




GEAR PUMP




Machine Operation


The aggregate belt and the emulsion pump are mechanically tied together to ensure a consistent mix.



Machine Operation



10 lbs emulsion
100 lbs rock = 10%




ROCK
100 LBS


EMULSION
10 LBS

How do we calibrate?

- For systems with positive displacement pumps, the gate setting of the hopper is varied to achieve different emulsion/aggregate ratios.




How do we calibrate?



10 lbs emulsion
83.3 lbs rock

= 12%



ROCK
83.3 LBS

EMULSION
10 LBS

How do we calibrate?

- **How do we determine that a 3.3 inch gate setting was required to get a 12% mix design?**
- **That will be covered with the demonstrator machine and calibration example we'll do next.**

Effects of water on rock calibration.

- **Moisture content describes the amount of moisture in the rock. When calibrating, we want to weigh only the rock.**

$$\text{Moisture content} = \frac{(\text{weight of wet rock} - \text{weight of dry rock})}{(\text{weight of wet rock})}$$

Calibration

Questions?

Thank You!