

## ORD Support Log

Issue	Solution/Comment	Version	Date Reported	Priority	Date Fixed	Fixed By:
Need a Workflow or Video created on how to migrate files in projectwise from different phases to retain reference links.	Create Workflow write-up	10.09.00.91	1/20/2021	High	3/3/2021	JG
Need Plan, Profile and Cross Section Label Cells need a proposal size	Create appropriate annotation groups as needed	10.09.00.91	2/25/2021	Low	NA	BPS
Prepare New Sheet borders for upcoming release	Create New Sheet seeds place in folder and move old Sheet Seeds to different folder so that both can be used. <span style="background-color: yellow;">■</span> Sheet Seeds 7/14/2021 12:53 PM File folder <span style="background-color: yellow;">■</span> Sheet Seeds First Gen 7/14/2021 10:28 AM File folder	10.09.00.91	2/25/2021	High	5/20/2021	BPS-MAS
Layout Sheet Does not have linked text nodes to the Work set		10.09.00.91	2/25/2021	High	3/15/2021	BPS-MAS
Need to Create New 50 Scale Plan sheet seed for proposal	Remove 20 from the proposal sheet seed NAME.	10.09.00.91	2/25/2021	Low	6/7/2021	BPS
Typical Section Sheet Seed Issues this sheet is shifted		10.09.00.91	2/25/2021	High	3/15/2021	BPS
Roll Plot Profile Sheet seed	Create New Drawing Seed Profile Sheet Roll Plot	10.09.00.91	2/25/2021	Med	4/7/2021	BPS
Cross Section existing ground line not displaying property in Cross sections	Bentley provided stop gap fix for this KYTC needs to implement	10.09.00.91	2/25/2021	High	6/7/2021	BPS
Pavement Markings Element templates they are pointing to the wrong linestyle.	Check all Pavement Marking Element Templates	10.09.00.91	2/25/2021	Med	4/9/2021	BPS
Create button for civil check this Button will help support	Create Button for Civil Display Browser	10.09.00.91	2/25/2021	Low	4/8/2021	BPS
Internet links under KYTC web when activated locks the program up and force a reboot.	Solution is to set the default browser to Internet Explorer	10.09.00.91	2/25/2021	High	3/15/2021	BPS
Remove Unused VBA with Next Release	Remove Unused VBA before next Release	10.09.00.91	2/25/2021	Low	6/7/2021	BPS
Microstation Connect users not getting Element Templates	Modify KYTC_Standards_OC.cfg to include MS_DGNLIBLIST_ELEMENTTEMPLATES > \$(CIVIL_ORGANIZATION_STANDARDS)Dgnlib/Feature Definitions/*.dgnlib	10.09.00.91	3/9/2021	High	3/10/2021	BPS
Multiple Feature definitions for Right of way Under that Alignment Category we have the following . PR Control of Access, PR Control of Access S_O, PR Easement, PR Easement S_O, PR Entrance, PR Right of Way, PR Right of Way S_O, PR Working Easement, PR Working R/W Line. We have very Similar Feature Definitions for Right of Way under Linear, PR R/W PR Easement, PR Easement S_O, PR Fence COA, PR Grave Relocation, PR ROW Line, PR Row Monument.		10.09.00.91	3/11/2021	MED	6/7/2021	BPS
When annotating cross sections the existing ground line does not annotate.	Revise the KYTC_Features_Levels_Element Templates_Annotations.dgnlib under the Feature Definitions - Corridor - PR Corridor and PR Corridor_Contours under the Display Settings change the Include Null Points Linear Features Display from False to True in both files.	10.09.00.91	4/6/2021	High	4/8/2021	BPS
Create video on how to Annotate Ground line on cross sections	Video created	10.09.00.91	4/8/2021	High	4/8/2021	BPS
Need 200 scale Alignment for right of way strip map	Create 200 scale annotation Group and associated goodies	10.09.00.91	4/8/2021	Med	6/9/2021	BPS
When creating a typical section sheet using the Place Named Boundary>From Drawing Boundary>Typical Section option, the sheet seed appears to have the sheet border dropped. The County, Item No. & Sheet No. headings are missing.	It is dropped but so are the other ones, it's only missing the text information	10.09.00.91	4/5/2021	High	5/17/2021	BPS
Layout sheet or Legend sheet cell does not appear to be set up to harvest data from WorkSet Properties such as project numbers, project manager, county and item number. The sheet information in the upper right corner (County, Item #, Sheet #) is functioning as expected, but the other instances of this data on the layout sheet does not appear to be set up.		10.09.00.91	4/5/2021	High	5/18/2021	MAS
It appears that the Named Boundary for creation of the Legend sheet is set to a sheet size of greater than 22"x36". The sheet as drawn in the sheet model is at the proper proportions.		10.09.00.91	4/29/2021	High	5/17/2021	BPS
Create an annotation group for PR Centerline 20-50 Scale that will annotate stations at 50' intervals and elevations at 2' intervals.	Create New Profile Annotation Group, Create new sheet seed for both old and new standards.	10.09.00.91	4/5/2021	High	5/25/2021	BPS
When creating drawing models, the reference container is attached "Live Nested" with Display Overrides set to "Always". Request that the Display Overrides be changed to "Never" to force ORD to look back to the main container to determine what levels are displayed.		10.09.00.91	4/5/2021	High	6/7/2021	MAS
PR Centerline 100 Scale feature definition is not set up correctly in profile.		10.09.00.91	4/5/2021	High	5/21/2021	BPS
Request PR Centerline 50 Scale stationing be adjusted to 500' majors and 100' minors. A 50 scale plan sheet will show ~1500' of alignment. Current settings have it annotated at 100' majors meaning you will have 16 stations across the top of your sheet.		10.09.00.91	4/5/2021	High	5/20/2021	BPS

Can the civil cell construction and reference levels be set to not plot? R_OR_CIVIL_CELL_REFERENCE_PR, R_OR_CIVIL_CELL_CONSTRUCTION_LEVEL_1, R_OR_CIVIL_CELL_CONSTRUCTION_LEVEL_2		10.09.00.91	4/5/2021	High	5/5/2021	BPS
For the PR Corridor feature definition, need to set the "Include Null Point Linear" to "True" to enable the annotation of existing centerline elevations.		10.09.00.91	4/5/2021	High	6/2/2021	BPS
For cross section annotation, the 10 Scale Full Size All annotation group is not set up to annotate the proposed easements. Also, it is not set up to annotate the proposed R/W is using the "PR Right of Way" feature definition under the "Alignments" folder. Verify that other scale annotations are not set up similarly.	revised annotation group to include OR (point_feature_definition = "Alignment\PR Right of Way") and Easement	10.09.00.91	4/29/2021	High	6/7/2021	BPS
There is not an element template set up for the annotation of proposed easement lines in cross section sheets.	Added to Annotation Groups	10.09.00.91	4/29/2021	High	6/7/2021	BPS
Recommend to increase the transparency on the profile and cross section gridlines to 70% for minor gridlines and 40% for major gridlines.	Modify KYTC_Features_Levels_Element Templates_Annotations.dgnlib	10.09.00.91	4/29/2021	High	5/20/2021	BPS
Legend sheet has text that is on default level	Change level to R_MS_SUMTXT_PT	10.09.00.91	5/17/2021	High	5/18/2021	BPS
PR Centerline 50 Scale feature definition annotation: <ul style="list-style-type: none"> <li>Stationing placed on R_PL_PCLTIC_PR level</li> <li>Bearing placed on R_PL_PSTA_PT level</li> </ul>	Check CL annotations to verify on correct level	10.09.00.91	4/5/2021	High	6/7/2021	BPS
KyGeonet FTP Access blocked due to Browser Upgrades	Revise written workflow Downloading Lidar Tiles with directions including how to install and use FTP Clients to access the files	10.09.00.91	4/21/2021	High	4/26/2021	BPS
County line linestyle has been deleted from the RSC file	Add County line linestyle back to the cad standards.	10.09.00.91	4/29/2021	MED	5/6/2021	BPS
Ditches on profiles not annotating	Create the following annotation groups and assign them to the feature definition. DT LT Annotation, DT RT Annotation, Dt Median Annotation These are all for profile.	10.09.00.91	4/27/2021	High	4/28/2021	BPS
Construction elements and fill not showing on plan sheets.	Construction elements should not plot. Check fill in the sheet seeds to see if it is turned on.	10.09.00.91	4/27/2021	MED	6/7/2021	BPS
Nested reference level display does not work like it says it should. Settings are not honored and behavior is inconsistent.	Fix in Design Seed and Sheet Seeds	10.09.00.91	4/27/2021	High	6/7/2021	MAS
Cross Sections are missing Some slopes and lane dimensions	Fix Annotation Group to exclude point1_on_top AND point2_on_top	10.09.00.91	5/26/2021	High	5/28/2021	BPS
The following Cells are being displayed on Cross Sections half size	The following cells were created for proposal use PXSES, EXSES, EX.PL add Proposal to these cell Names and create new cells that are twice the proposal size. PXSES, EXSES, EX.PL	10.09.00.91	6/4/2021	High	6/4/2021	BPS
Needed some point feature definitions added.	Added the following feature definitions: PR ROW Monument, EX ROW Monument, EX Property Owner, EX Property Owner Historic, EX Property Owner Mineral, EX Property Owner Historic Mineral.	10.09.00.91	6/4/2021	Med	6/18/2021	EKS
Need Button for GuideSign Plus	Button Added for GuideSign Plus	10.09.00.91	7/16/2021	Med	7/16/2021	MAS