



Pratt Truss 1, L0 bearing north side of pin



Pratt Truss 1, L0 bearing
Close-up north side with deformation of plate, plus rivet head failing.